PHOTOS OF SG 6186A



Left View of SG 6176A



Right View of SG 6176A

Left and right view of the vehicle could not be fully captured due to spatial constraints at the site.



Zoomed In View of SG 6176A

Damage Assessment: Bus's RHR side camera damaged.

SCHEMATIC DIAGRAM OF INCIDENT



${\tt SECURITY\ CLASSIFICATION\ \backslash\ SENSITIVITY\ CLASSIFICATION}$

		STATEMEN	NT OF ACCUS	ED			
STATEMENT OF	M/	ATTHEW CHUA H	OF SIN		ALIASES	s	
NRIC NO	S 439J			MALE/FEMALE		MALE	
EMPLOYMENT	NSF	DRIVING LICENSE NO	SAF/TPT/014	11/21	NATIONALITY		SINGAPOREAN
DIALECT	HOKKIEN	LANGUAGE SPOKEN	ENGLISH/CH	INESE	TEL NO		
ADDRESS							
INTERPRETED BY	RANK	TIME		DATE		SIGN	r
RECORDED BY	RANK	TIME		DATE		SIGN	
a 5 minutes break, we m mirror came into contact ton's left kerb mirror wa Prior to the above mentio down my vehicle to main bus's right rear was sligh my lane temporarily. Ho could pass the bus witho protrusion which I then s After the incident, 3SG I instructions.	with the right rear s s broken. oned situation, I kept ntain a safe distance of the protruding. I the wever, there were 2 out adjusting into the tepped on the brakes	t a safe following di away from the bus, in checked if the Ian cars which rendere e right side of my is sharder but it was to	S bus (\$G6176A). stance from the SE. As the bus turned are on my right was sed me unable to dilane, In addition, soo late.	The SB 3S bus. A l and sto s clear w o so. I th	S bus's right real As the bus signal pped at the bus s ith an intention then made an ass smond had also	led left, stop, I re to move sessment alerted	I proceeded to slove ealised that the SBS to the right side of t and deemed that me about the bus's
DATE		171121	SIGNA DRIVER	TURE O			

STATEMENT OF 3SG DESMOND TOK RU XIANG

		STATEMEN	T OF ACCUSED		
STATEMENT OF	DE	SMOND TOK RU	XIANG	ALIASES	
NRIC NO	S9 324C	AGE	22	MALE/FEMALE	MALE
EMPLOYMENT	REG	DRIVING SAF/TPT/N/00205/21 LICENSE NO		NATIONALITY	SINGAPOREAN
DIALECT		LANGUAGE SPOKEN	ENGLISH/CHINESE	TEL NO	
ADDRESS					
INTERPRETED BY	RANK	TIME	DATE		SIGN
RECORDED BY	RANK	TIME	DATE	,	SIGN
at 1842 hrs along Loyan; SBS bus had signalled the off to the TO to slow down the 5 ton would be able to the 5 ton would be able	g ave. The incident r hat it will be stoppin wn and to watch out to make it past the bu	esuited in damage to g at the bus stop and for the SBS bus on t as.	ight rear was slightly proto the 5 ton's left side kert I from there the TO had a he left. The TO was also a the side of the road and	o mirror and the bus dso began slowing of aware of the bus's pa	's right rear camera. The lown. I had also sounded rotrusion and judged that
DATE		171121	SIGNATURE (DRIVER/WITN	7151.01-1	B





Police Station Of Origin. Bedok South N.P.C 20 Chai Chee Drive SINGAPORE 469045 1 cC3 Report No. T/2021 1117/2083

Tel No: 1800-2448999

DEDART	CVCA	TO ACCUO	ACCIDENT
REPUBLI	L 20 14	DESCRIPTION OF	ACCIDENT

	ne Report I 321 19:56	Made:	Vide Report No.:	Station Diary No., 30
Informa	nt's Partic	ulars		
7,000,000,000	Informant EW CHUA		Address:	
ID Type / ID No.: NRIC NO.: 3 439J		3 9 J	Contact No.: Home/Office:	Mobile:
National SINGAP	ily. PORE CITIZ	EN	Email:	
Sex: Male	Age: 23	Date of Birth. 09/05/1998	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: NATIONAL SERVICE MAN (SAF)		CE MAN (SAF)	Driving Licence Information: Class: 3.4	Date of Expiry:

Type of Accident:	Non-Injury Government Vehi	Drink cle Drive No	Date/Time of Accident: 17/11/2021 10:40	Type of Location Straight Road	
Location: LOYANG AVI	ENUE				
233000000		Road Surface: Wat		Road Speed Limit	
[A170] C = A170] [197].		Traffic Control:		Traffic Volume: Heavy	
Traffic Flow One Way		Not Controlled		Heavy	

Details of V	ehicle Involved				- Carrier	主以 标准分别准备则。
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
MID21312	SAF MILITARY VEHICLE				Slightly Damaged	0
SG6176A	Bus/Coach/Mi nibus				Slightly Damaged	0

Part 2 of 3



Part 3 of 3



