

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21013048/ATY3E2

Date: 29/03/2022

REFERENCE

Insured/Claimant:	ZHOU MENG	Policy No:	1900021928		
Date of Loss:	17/12/2021	Nature of Claim:	OD	Claim No:	4983358943SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP6004Y	Engine No:	CHZC26224
Make & Model:	AUDI A3, 999cc SEDAN TFSI (A)	Chassis No:	WAUZZZ8V6K1014173
Reg. Date:	25/02/2019 (Man. Year: 2018)	Odometer:	22568 km
Colour:	Silver		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$93,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,302.00	1,201.36	11,100.64	90.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,852.00	1,242.00	1,610.00	56.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,154.00	2,443.36	12,710.64	83.88
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	14,554.00	1,843.36	12,710.64	87.33
+ GST 7.00/7.00% (S\$)	1,018.78	129.04	889.74	87.33
Nett Amount (S\$)	15,572.78	1,972.40	13,600.38	87.33

INSPECTION

Date of Assignment:	23/12/2021		
Date Inspected:	22/12/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,987.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	39.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	160.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	536.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	297.00 FS	*- FS
7	1		*FRONT BUMPER TRIM COVER - RH	Not Necessary	163.00 FS	*- FS
8	1		*FRONT WHEEL HOUSING LINER ADAPTER - RH	Not Necessary	38.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	191.00 FS	*- FS
11	1		*SIGN CAUTION	Necessary	14.00 FS	*10.88 FS
12	1		*AIR COND STICKER	Necessary	8.00 FS	*5.68 FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	189.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Not Necessary	122.00 FS	*- FS
15	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	795.00 FS	*- FS
16	1		*HORN LOW TONE - RH	Not Necessary	200.00 FS	*- FS
17	1		*RADIATOR AIR GUIDE - RH	Not Necessary	25.00 FS	*- FS
18	1		*RADIATOR SEAL OUTER - RH	Not Necessary	8.00 FS	*- FS
19	1		*RADIATOR AIR GUIDE UPPER - CENTER	Not Necessary	12.00 FS	*- FS
20	1		*HEADLIGHT - RH	Not Necessary	5,455.00 FS	*- FS
21	1		*HEADLIGHT WASHER ASSY - RH	Not Necessary	142.00 FS	*- FS
22	1		*LIFT CYLINDER HOSE	Not Necessary	68.00 FS	*- FS
23	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
24	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 12,302.00 1,201.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
4	TO RESPRAY FRONT BUMPER	New	900.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,852.00	1,242.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >