

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21013049/AQY3N2**Date:** 23/03/2022**REFERENCE**

Insured/Claimant:	LIU YI	Policy No:	1700070654-04		
Date of Loss:	17/12/2021	Nature of Claim:	OD	Claim No:	6810218832SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT4377P		Engine No:	CWG042893
Make & Model:	AUDI S5 SPORTBACK, 3.0 TFSI QUATTRO (A)		Chassis No:	WAUZZZF50JA037465
Reg. Date:	28/10/2017 (Man. Year: 2017)		Odometer:	15604 km
Colour:	Grey			
Engine Capacity:	2995 cc			
Market Value/New Car Price:	S\$252,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35R19	Rear Tyre Size:	255/35R19
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,641.00	5,337.36	17,303.64	76.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,672.00	2,272.00	3,400.00	59.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,313.00	7,609.36	20,703.64	73.12
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	26,313.00	5,609.36	20,703.64	78.68
+ GST 7.00/7.00% (S\$)	1,841.91	392.66	1,449.25	78.68
Nett Amount (S\$)	28,154.91	6,002.02	22,152.89	78.68

INSPECTION

Date of Assignment:	23/12/2021		Premium Automobiles Pte Ltd (UBI)
Date Inspected:	22/12/2021	Inspected At:	55 Ubi Road 1
			Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	2,941.00 FS	*2,352.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	407.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Not Necessary	511.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	228.00 FS	*- FS
6	2		*FRONT BUMPER AIG GUIDE-LH/RH	Not Necessary	126.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	3,508.00 FS	*2,806.40 FS
8	2		*FRONT PARKING AID SENSOR SUPPORT-LH/RH	Not Necessary	102.00 FS	*- FS
9	1		*RADIATOR GRILLE UPPER COVER	Not Necessary	189.00 FS	*- FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	736.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	124.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	845.00 FS	*- FS
13	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	72.00 FS	*- FS
14	1		*FRONT BUMPER TOP COVER	Torn	127.00 FS	*101.60 FS
15	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
16	1		*AIR COND STICKER	Necessary	8.00 FS	*5.68 FS
17	1		*FRONT LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS
18	2		*FRONT LOCK CARRIER SUPPORT-LH/RH	Not Necessary	58.00 FS	*- FS
19	4		*POP RIVET	Not Necessary	4.00 FS	*- FS
20	1		*HORN-RH	Not Necessary	126.00 FS	*- FS
21	1		*HORN BRACKET-RH	Not Necessary	29.00 FS	*- FS
22	2		*FRONT PARKING AID SENSOR-INNER/OUTER (NPA)	Not Necessary	0.00 FS	*- FS
23	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	9.00 FS	*- FS
24	1		*BONNET	Repair	3,312.00 FS	*- FS
25	3		*BONNET IMPACT PROTECTION-CENTER/LH/RH	Not Necessary	84.00 FS	*- FS
26	1		*BONNET STRIKER-RH	Not Necessary	50.00 FS	*- FS
27	1		*BONNET LOCK	Not Necessary	214.00 FS	*- FS
28	1		*HEADLIGHT-RH	Not Necessary	7,902.00 FS	*- FS
29	1		*LIFT CYLINDER-RH	Not Necessary	198.00 FS	*- FS
30	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	86.00 FS	*- FS
31	2		*RADIATOR AIR GUIDE RH-INNER/OUTER	Not Necessary	47.00 FS	*- FS
32	1		*RADIATOR AIR GUIDE UPPER	Not Necessary	16.00 FS	*- FS
33	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
34	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 22,641.00 5,337.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR.HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER.BONNET AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,400.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,200.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,672.00	2,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >