



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2204281
3 ANSON ROAD #16-00	INV Date	13/07/2022
SPRINGLEAF TOWER	Reference	CC6/CTI21013050/Kga3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	SDR 6638D
Insured Veh.	SMS 2352S
Claim No.	SNM21D207367
Policy No.	DMPCSNW00245092101
Accident Date	16/12/2021
Inspection Date	21/12/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI21013050/Kga3q2 Date: 13/07/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMS 2352S	Veh. Inspected	SDR 6638D
Policy No.	DMPCSNW00245092101	Coverage (\$)	0.00
Claim No.	SNM21D207367	Excess (\$)	0.00
Assign From		Assign Date	21/12/2021
2. Vehicle Particulars & Condition			
Make & Model	NISSAN QASHQAI (A)	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	SJNFBAJ11U1795383	Colour	METALLIC PEARL WHITE
Odometer	49328 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R19	BRIDGESTONE	4 mm
L/H Front Tyre	225/45 R19	BRIDGESTONE	4 mm
R/H Rear Tyre	225/45 R19	BRIDGESTONE	3 mm
L/H Rear Tyre	225/45 R19	BRIDGESTONE	3 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/12/2021	Inspection Date	21/12/2021
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDR 6638D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER (N)	BENT	796.70	796.70
1	REAR BUMPER REINFORCEMENT (N)	BENT	691.50	619.20
1	REAR BUMPER TOW COVER (N)	SERVICEABLE	38.80	-
2	REAR BUMPER RETAINER @\$38.90 (N)	O/S DISTORTED	77.80	38.90
4	REAR BUMPER SENSOR @\$350.00 (N)	DENTED / SHORTED (3 PCS ONLY)	1,400.00	855.00
1	RH REFLECTOR (N)	SERVICEABLE	61.90	-
1	TAILGATE LOCK (N)	TO REPAIR SEE LABOUR	190.50	-
1	TAILGATE EMBLEM (N)	NECESSARY	94.40	94.40
1	TAILGATE WEATHERSTRIP (N)	SERVICEABLE	167.80	-
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	482.60	-
1	REAR TOP GARNISH (N)	DENTED	88.10	88.10
1	EXHAUST MUFFLER (N)	TO REPAIR SEE LABOUR	954.50	-
	LESS 10% DISCOUNT		-504.46	-249.23
			4,540.14	2,243.07
<b><u>LABOUR</u></b>				
	TO INSTALL REVERSE SENSOR .		50.00	50.00
	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE LOCK,REAR END PANEL AND EXHAUST MUFFLER.		650.00	400.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		700.00	600.00
			1,400.00	1,050.00
<b>GRAND TOTAL</b>			<b>5,940.14</b>	<b>3,293.07</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,200.00</b>
---	--	--	-----------------

Report Ref No. CC6/CTI21013050/Kga3q2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SDR 6638D

## INSPECTION






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SDR 6638D

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SDR 6638D**

**RE-INSPECTION**

