

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21013053/UEA3Q2**Date:** 02/06/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLJ9251M**Insured Vehicle No :** GBD3615L

Date of Loss: 18/12/2021

Nature of Claim: TP

Claim No: 8867968758SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLJ9251M**

Make & Model: NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A)

Engine No: HR16992819B

Reg. Date: 30/12/2016 (Man. Year: 2016)

Chassis No: MNTBBAB17Z0027880

Colour: Brown

Odometer: 75235 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16

Rear Tyre Size: 195/60 R16

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,962.98	10,553.06	6,409.92	37.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,240.00	5,730.00	4,510.00	44.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,202.98	16,283.06	10,919.92	40.14
Approved Total (Overridden) (S\$)		13,000.00		
Nett Amount (S\$)	27,202.98	13,000.00	14,202.98	52.21
+ Medical Costs (S\$)		1,108.03		
+ Car Rental (24.0 x S\$100.00/day) (S\$)		2,400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		16,515.48		

INSPECTION

Date of Assignment: 23/12/2021

Date Inspected: 23/12/2021

Inspected At:

Sin Hwee Motor Pte Ltd (HQ)
Blk 3023A, Ubi Road 1, #01-59
Singapore 408717

Estimated Period of Repair: 18.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	1,229.90 FL	*716.80 FL
2	2		*BOOTLID HINGE	Bent	198.00 FL	*198.00 FL
3	1		*SYLPHY LOGO	Necessary	103.00 FL	*75.20 FL
4	1		*CENTER LOGO	Necessary	79.00 FL	*45.80 FL
5	1		*PURE DRIVE LOGO	Necessary	96.00 FL	*96.00 FL
6	1		*BOOTLID CHROME (TOP)	Cracked	196.60 FL	*196.60 FL
7	1		*BOOTLID CHROME (BOTTOM)	Bent / Cracked	112.00 FL	*112.00 FL
8	1		*BOOTLID LAMP L/H	Cracked	160.90 FL	*160.90 FL
9	1		*BOOTLID LAMP R/H	Cracked	160.90 FL	*160.90 FL
10	1		*BOOTLID INNER TRIM	Distorted	181.80 FL	*147.60 FL
11	1		*BOOTLID LOCK	Bent	215.00 FL	*166.00 FL
12	1		*WEATHERSTRIP	Twisted	172.00 FL	*93.50 FL
13	1		*REAR WINDSCREEN	Serviceable	1,716.80 FL	*- FL
14	1		*L/H REAR QUARTER GLASS	Necessary	545.20 FL	*545.20 FL
15	1		*REAR CHASSIS MEMBER N/S	Crumpled / Buckled	654.22 FL	*450.00 FL
16	1		*FLOORBOARD PANEL	Crumpled / Buckled	909.60 FL	*812.30 FL
17	1		*SPARE TYRE TOP SPONGE	Torn	291.55 FL	*182.70 FL
18	1		*SPARE TYRE TOP BOARD	Distorted	486.30 FL	*486.30 FL
19	1		*SPARE TYRE TOP MAT	Not Necessary	256.87 FL	*- FL
20	1		*REAR L/H FENDER	Badly Buckled /Buckled	1,508.00 FL	*1,508.00 FL
21	1		*REAR L/H FENDER INNER PANEL	Repair	404.00 FL	*- FL
22	1		*REAR L/H WHEEL HOUSE PANEL	Repair	440.87 FL	*- FL
23	1		*REAR L/H FENDER INNER COVER	Distorted / Torn	158.11 FL	*158.11 FL
24	1		*REAR L/H MUD FLAG	Torn	68.00 FL	*68.00 FL
25	1		*REAR EXHAUST BOX	Dented / Bent	1,148.00 FL	*1,148.00 FL
26	1		*REAR WHEEL AXLE	Not Necessary	1,283.60 FL	*- FL
27	1		*REAR ABSORBER L/H	Not Necessary	358.00 FL	*- FL
28	1		*REAR ABSORBER R/H	Not Necessary	358.00 FL	*- FL
29	1		*TAILLAMP L/H	Cracked	421.90 FL	*416.00 FL
30	1		*TAILLAMP R/H	Cracked	421.90 FL	*416.00 FL
31	1		*TAILLAMP PANEL L/H	Bent	145.00 FL	*145.00 FL
32	1		*TAILLAMP PANEL R/H	Dented	145.00 FL	*145.00 FL
33	1		*REAR BUMPER	Distorted	669.00 FL	*669.00 FL
34	2		*REAR BUMPER SIDE RETAINER	Cracked	104.00 FL	*70.00 FL
35	3		*REAR BUMPER SPONGE	Torn	297.60 FL	*297.60 FL
36	1		*BOOTLID LOCK SENSOR	Cracked	172.00 FL	*172.00 FL
37	1		*REAR BUMPER REFLECTOR (LH)	Broken	69.00 FL	*69.00 FL
38	1		*END PANEL	Badly Dented	565.70 FL	*467.90 FL
39	1		*END PANEL TOP GARNISH	Distorted	144.21 FL	*105.10 FL
40	1		*REAR FENDER INNER TRIM L/H	Distorted	414.00 FL	*414.00 FL
41	1		*REAR FENDER INNER TRIM R/H	Serviceable	414.00 FL	*- FL
42	1		*SET NUMBER PLATE AND HOLDER	Bent	110.00 FS	*40.00 FS
43	1		*CLIPS (30 PCS)	Necessary	135.00 FS	*80.00 FS
44	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
45	1		*SET REVERSE CAMERA	Shorted	450.00 FS	*300.00 FS
46	1		*WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
47	1		*SET WINDSCREEN INNER SEAL	Necessary	80.00 FS	*40.00 FS
48	1		*QUARTER GLASS SEALANT (N/S)	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,710.53	11,644.51
- List Item Discount on L Items 10.00/10.00% (\$)	1,747.55	1,091.45
Total Parts (\$)	16,962.98	10,553.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING SERVICE KING ROLLER	New	200.00	90.00
2	INSTALL AND CALIBRATE REVERSE SENSOR	New	80.00	50.00
3	INSTALL AND CALIBRATE REVERSE SENSOR	New	150.00	0.00
4	TO REMOVE AND REPLACE REAR WINDSCREEN	New	200.00	120.00
5	TO REMOVE AND REPLACE REAR QUARTER GLASS	New	90.00	80.00
6	TO MOUNT VEHICLE ON CAR O LINER TO SET UP REPAIR TOOL AND MEASUREMENT EQUIPMENT	New	350.00	300.00
7	TO REMOVE AND REFIX INNER TRIM ,LEATHER SEATS ,ROOF LINING AND CARPET TO FACILITATE REPAIR WORK	New	380.00	100.00
8	TO DISMOUNT AND REPLACE REAR WHEEL AXLE AND ABSORBER	New	680.00	0.00
9	TO REPLACE REAR FENDER ,CHASSIS FRAME ,FLOORBOARD AND END PANEL INCLUDE KNOCKING ,CUTTING AND WELDING TO REPLACE INSTALL AND ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC	New	4,500.00	3,000.00
10	TO REPLACE AND ALIGN REAR EXHAUST BOX	New	180.00	60.00
11	TO DISMOUNT PETROL TANK TO FACILITATE REPAIR WORK	New	180.00	60.00
12	TO CARRY OUT COMUTERIZED 4 WHEEL ALIGNMENT	New	150.00	60.00
13	TO TRANSFER BOOTLID MECHANISM AND FITTINGS TO NEW BOOTLID	New	200.00	60.00
14	TO SPRAY PAINT REAR DOOR ,REAR BUMPER ,BOOTLID ,END PANEL,FENDER ,CHASSIS FRAME AND FLOORBOARD	New	2,300.00	1,600.00
15	TO SUPPLY AND TUFF KOTE	New	380.00	120.00
16	TO CARRY OUT WIRE CHECKING	New	220.00	30.00
Gross Labour Cost (\$\$)			10,240.00	5,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >