

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21013054/AQY3E2

Date: 24/06/2022

REFERENCE

Insured/Claimant:	JASON SAMUEL WILLIAMS	Policy No:	2070152652	
Date of Loss:	16/12/2021	Nature of Claim:	OD	Claim No: 1079154909SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV9866P		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZDC06646
Reg. Date:	29/10/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF30M1012858
Colour:	Black	Odometer:	18516 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,303.00	4,087.92	11,215.08	73.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,072.00	3,122.00	2,950.00	48.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,375.00	7,209.92	14,165.08	66.27
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	20,575.00	6,409.92	14,165.08	68.85
+ GST 7.00/7.00% (S\$)	1,440.25	448.69	991.56	68.85
Nett Amount (S\$)	22,015.25	6,858.61	15,156.64	68.85

INSPECTION

Date of Assignment:	23/12/2021		
Date Inspected:	22/12/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,008.00 FS	*806.40 FS
2	1		*FRONT BUMPER CONNECTING PIECE	Not Necessary	145.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	59.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Deformed	217.00 FS	*173.20 FS
5	1		*FRONT BUMPER GRILLE LOWER COVER	Not Necessary	51.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE	Damaged	110.00 FS	*98.80 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
8	1		*FRONT BUMPER SPOILER	Cut	383.00 FS	*306.40 FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	153.00 FS	*- FS
10	1		*FRONT BUMPER BRACKET	Not Necessary	21.00 FS	*- FS
11	1		*RADIATOR GRILLE	Cracked	1,433.00 FS	*1,146.40 FS
12	1		*RADIATOR STRIKER PLATE	Cracked	244.00 FS	*194.80 FS
13	1		*RADIATOR GRILLE COVER	Not Necessary	45.00 FS	*- FS
14	1		*RADIATOR BRACKET	Not Necessary	41.00 FS	*- FS
15	1		*FRONT CAMERA	Not Necessary	1,141.00 FS	*- FS
16	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	102.00 FS	*- FS
17	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	916.00 FS	*- FS
18	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	39.00 FS	*- FS
19	1		*FRONT BUMPER TOP COVER	Cracked	123.00 FS	*98.00 FS
20	1		*SIGN CAUTION	Necessary	14.00 FS	*10.88 FS
21	1		*AIR CON STICKER	Necessary	8.00 FS	*5.68 FS
22	1		*HORN - HIGH TONE LH	Not Necessary	137.00 FS	*- FS
23	1		*HORN BRACKET - LH	Not Necessary	22.00 FS	*- FS
24	2		*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
25	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	9.00 FS	*- FS
26	1		*SET FRONT BUMPER WIRING	Not Necessary	676.00 FS	*- FS
27	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	240.00 FS	*- FS
28	1		*FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS	Not Necessary	101.00 FS	*- FS
29	1		*FRONT FENDER TOP COVER - LH	Not Necessary	16.00 FS	*- FS
30	1		*HEADLIGHT MOUNTING	Cracked	118.00 FS	*94.40 FS
31	1		*HEADLIGHT - LH	Not Consistent With The Impact	5,589.00 FS	*- FS
32	1		*LIFT CYLINDER - LH	Not Necessary	210.00 FS	*- FS
33	1		*HEADLIGHT HOSE	Not Necessary	80.00 FS	*- FS
34	2		*FRONT WHEEL ARCH COVER - LH / RH	Necessary	536.00 FS	*428.80 FS
35	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	7.00 FS	*- FS
36	1		*HEADLIGHT MOUNTING - RH	Cracked	118.00 FS	*94.40 FS
37	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
38	1		*SUNDRIES	Necessary	250.00 FS	*18.00 FS
39	2		*RADIATOR AIR GUIDE - LH / RH (Supplementary)	Cracked	86.00 FS	*68.16 FS
40	1		*A/C CONDENSER (Supplementary)	Dented	605.00 FS	*483.60 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 15,303.00 4,087.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPEATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
4	TO RESPRAY FRONT BUMPER AND FRONT FENDER	New	2,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO REMOVE AND RENEW AIRCON CONDENSER. TO CARRY OUT VACUUM AND REGAS FOR A1234	New	1,400.00	1,400.00
(Supplementary)				
Gross Labour Cost (\$\$)			6,072.00	3,122.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >