

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21013060/DTF3N2**Date:** 28/01/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29149085ACY
Claimant Vehicle No :	SKU3502H	Insured Vehicle No :	YP1182X
Date of Loss:	22/12/2021	Nature of Claim:	TP
		Claim No:	639447

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU3502H	Engine No:	3ZZ4816508
Make & Model:	TOYOTA COROLLA, 1.6 (A)	Chassis No:	MR053ZEE106125055
Reg. Date:	13/02/2009 (Man. Year: 2008)	Odometer:	299822 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	Maxxis 5 mm	Rear Right Side:	Maxxis 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,153.57	2,843.76	15,309.81	84.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,820.00	1,700.00	5,120.00	75.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	24,973.57	4,543.76	20,429.81	81.81
Approved Total (Overridden) (\$\$)		3,600.00		
(\$\$)	24,973.57	3,600.00	21,373.57	85.58
+ GST 7.00/7.00% (\$\$)	1,748.15	252.00	1,496.15	85.58
Nett Amount (\$\$)	26,721.72	3,852.00	22,869.72	85.58

INSPECTION

Date of Assignment:	23/12/2021	JWG International Pte Ltd (HQ)
Date Inspected:	23/12/2021 Inspected At:	Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
		AutoPoint
		Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: BRYAN TANI**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jan 2022)
Parts:	143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU3502H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	1,492.10 FL	*794.80 FL
2	2		*BOOTLID LAMP LH/RH	Mounting Cracked	1,396.20 FL	*872.00 FL
3	1		*BOOTLID LOGO	Necessary	79.20 FL	*68.00 FL
4	1		*BOOTLID 1.6 EMBLEM	Necessary	59.20 FL	*59.20 FL
5	1		*BOOTLID LX EMBLEM	Necessary	66.29 FL	*66.29 FL
6	1		*BOOTLID COROLLA EMBLEM	Necessary	61.98 FL	*32.00 FL
7	1		*BOOTLID ALTIS EMBLEM	Necessary	71.29 FL	*55.00 FL
8	1		*BOOTLID CENTER GARNISH CHROME MOULDING	Bent/Mounting Cracked	499.10 FL	*202.50 FL
9	2		*BOOTLID HINGE LH/RH	Not Necessary	196.40 FL	*- FL
10	1		*BOOTLID LOCK	Damaged	310.90 FL	*168.00 FL
11	1		*BOOTLID WEATHERSTRIP	Serviceable	384.20 FL	*- FL
12	2		*TAIL LAMP LH/RH	O/s Cracked/N/s Mtg Cracked	1,996.20 FL	*724.00 FL
13	2		*TAIL LAMP PANEL LH/RH	Not Necessary	939.60 FL	*- FL
14	2		*TAIL LAMP LOWER BRACKET LH/RH	Not Necessary	448.20 FL	*- FL
15	1		*REAR BUMPER	Distorted	942.90 FL	*482.03 FL
16	2		*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	156.58 FL	*- FL
17	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	356.20 FL	*- FL
18	1		*REAR BUMPER SPONGE	Not Necessary	258.10 FL	*- FL
19	1		*REAR REINFORCEMENT BAR	Not Necessary	340.90 FL	*- FL
20	2		*REAR BUMPER BRACKET LH/RH	Not Necessary	459.60 FL	*- FL
21	1		*REAR END PANEL	Not Necessary	1,592.80 FL	*- FL
22	1		*REAR END PANEL TOP GARNISH	Mounting Cracked	379.40 FL	*241.20 FL
23	1		*SPARE WHEEL PANEL	Not Necessary	1,649.20 FL	*- FL
24	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	399.84 FL	*- FL
25	2		*SPARE WHEEL QUARTER PANEL LH/RH	Not Necessary	699.60 FL	*- FL
26	1		*SPARE WHEEL TOOL BOX	Not Necessary	298.90 FL	*- FL
27	2		*REAR FENDER LH/RH	O/s Repair/N/s Not Necessary	2,980.20 FL	*- FL
28	2		*REAR FENDER INNER TRIM LH/RH	Not Necessary	1,196.58 FL	*- FL
29	1		*REAR EXHAUST PIPE	Not Necessary	1,380.80 FL	*- FL
30	1		*REAR EXHAUST MOUNTING	Not Necessary	128.10 FL	*- FL
31	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	159.80 FL	*- FL
32	1		*REAR WINDSCREEN MOULDING	Not Necessary	249.10 FL	*- FL
33	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
35	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
36	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
37	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
38	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
40	1		*REAR NO PLATE & CASING	Serviceable	100.00 FS	*- FS
41	1		*SET REVERSE SENSOR	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,479.46	3,785.02
- List Item Discount on L Items 20.00/25.00% (\$\$)	4,325.89	941.26
Total Parts (\$\$)	18,153.57	2,843.76

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	750.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	700.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	400.00	0.00
6	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
7	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	150.00	60.00
8	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	150.00	0.00
9	TO RNR REAR BUMPER SENSOT TO FACILITATE REPAIRS	New	120.00	40.00
10	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
11	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (S\$)			6,820.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >