

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21004991/R1TF3E2-1
Date: 11/01/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SLK4432K **Insured Vehicle No :** SLL8980M
Date of Loss: 16/04/2021 Nature of Claim: TP Claim No: MFL2021D0001858

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK4432K**
Make & Model: HONDA CIVIC, 1.6 VTI (A) Engine No: R16B21601175
Reg. Date: 17/01/2017 (Man. Year: 2016) Chassis No: MRHFC5650GT000861
Colour: White Odometer: 102777 km
Engine Capacity: 1597 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16 Rear Tyre Size: 215/55 R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,504.00	1,414.72	2,089.28	59.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,390.00	1,310.00	1,080.00	45.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,894.00	2,724.72	3,169.28	53.77
Approved Total (Overridden) (S\$)		2,150.00		
Nett Amount (S\$)	5,894.00	2,150.00	3,744.00	63.52

INSPECTION

Date of Assignment: 23/12/2021
Date Inspected: 22/04/2021 Inspected At: Empire Image Pte Ltd (HQ)
NO 4 PANDAN LOOP (BLK 1/ BLK K)
Singapore 128222
Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Jan 2022)
Parts: 143	HONDA CIVIC 1.6 VTI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK4432K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented / Bent	704.30 F	*531.20 FL
2	1		*BOOT LID OUTER GARNISH	Dented / Holder Cracked	109.90 F	*109.90 FL
3	1		*BOOT LID OUTER GARNISH CIVIC GARNISH	Necessary	12.00 F	*12.00 FL
4	1		*BOOT LID CENTRE EMBLEM	Necessary	13.30 F	*13.30 FL
5	1		*BOOT LID I-VTEC EMBLEM	Necessary	12.00 F	*12.00 FL
6	1		*BOOT LID LOCK	Serviceable	81.20 F	*- FL
7	1		*REAR BUMPER	Dented	883.10 F	*617.20 FL
8	1		*SET REAR BUMPER CLIPS	Necessary	75.00 F	*30.00 FL
9	1		*REAR BUMPER LOWER GARNISH	Dented / Cracked	39.80 F	*39.80 FL
10	1		*REAR BUMPER LH SIDE REVERSE SENSOR	Dented / Malfunctioned	145.80 F	*145.80 FL
11	1		*REAR BUMPER LH CENTRE REVERSE SENSOR	Not Necessary	145.80 F	*- FL
12	1		*REAR BUMPER RH CENTRE REVERSE SENSOR	Refit	145.80 F	*- FL
13	1		*REAR BUMPER RH SIDE REVERSE SENSOR	Refit	145.80 F	*- FL
14	1		*REAR BUMPER LH REFLECTOR COVER	Dented / Cracked	33.00 F	*8.50 FL
15	1		*REAR BUMPER REINFORCEMENT	Dented	180.00 F	*180.00 FL
16	1		*END PANEL	Repair	265.70 F	*- FL
17	1		*END PANEL INNER GARNISH	Refit	50.30 F	*- FL
18	1		*RAER ANTENNA SENSOR	Cracked	60.80 F	*60.80 FL
19	1		*LH TAIL LAMP ASSY	Refit	307.40 F	*- FL
20	1		*REAR BUMPER LH REFLECTOR	Cracked	23.00 F	*7.90 FL
21	1		*REAR NUMBER PLATE	Refit	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,504.00	1,768.40
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	353.68
Total Parts (S\$)	3,504.00	1,414.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO PANEL BEATING, STRAIGHTEN AND REALIGN ALL AFFECTED AREAS. TO REMOVE, CHECK, REINSTALL AND REPLACED PARTS	New	900.00	450.00
2	CHECK WIRING AND LIGHTING SYSTEM FOR PROPER FUNCTION	New	70.00	30.00
3	SPRAY ANTI RUST CHEMICAL TO REPAIRED AND REPLACED PANELS	New	70.00	30.00
4	REMOVE AND REINSTALL REAR INNER GARNISH AND TRIM TO FACILITATE REPAIRS	New	250.00	60.00
5	REMOVE, CHECK, REPLACE AND REINSTALL REAR BUMPER REVERSE SENSORS AND WIRE HARNESS TO FACILITATE REPAIRS	New	100.00	40.00
6	PUTTY AND SPRAY REPAIRED AND REPLACED BODY PANELS	New	1,000.00	700.00
			Gross Labour Cost (S\$)	2,390.00
				1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >