

Vehicle No : SLK 4432 K Honda Civic (A)
Workshop : Empire Image Pte Ltd

TP/0007/21

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist.%	Our Recommendation (S \$)	Dist.%
To Supply :					
1pc. Boot lid	Dented/bent	704.30		531.20	20
1pc. Boot lid outer garnish	Dented/holder Cracked	109.90		109.90	20
1pc. Boot lid outer garnish CIVIC garnish	Necessary	12.00		12.00	20
1pc. Boot lid centre emblem	Necessary	13.30		13.30	20
1pc. Boot lid I-VTEC emblem	Necessary	12.00		12.00	20
1pc. Boot lid lock	Serviceable	81.20		--	20
1pc. Rear bumper	Dented	883.10		617.20	20
1set rear bumper clips	Necessary	75.00		30.00	20
1pc. Rear bumper lower garnish	Dented/cracked	39.80		39.80	20
1pc. Rear bumper LH side reverse sensor	Dented/malfunctioned	145.80		145.80	20
1pc. Rear bumper LH centre reverse sensor xnn	Dented/malfunctioned	145.80		145.80	20
1pc. Rear bumper RH centre reverse sensor	Refit	145.80		--	20
1pc. Rear bumper RH side reverse sensor	Refit	145.80		--	20
1pc. Rear bumper LH reflector cover	Dented/cracked	33.00		8.50	20
1pc. Rear bumper LH reflector	Cracked	23.00		7.90	20
1pc. Rear bumper reinforcement	Dented	180.00		180.00	20
1pc. End panel	Dented/repair	265.70		--	20
1pc. End panel inner garnish	Refit	50.30		--	20
1pc. Rear antenna sensor	Cracked	60.80		60.80	20
1pc. LH tail lamp assy	Refit	307.40		--	20
Sub-Total :-		3,434.00		1768.40 1,914.20	
Total Discount :-		--		20% 382.84	
		3,434.00		1414.72 1,531.36	
Special Nett Items :-					
1pc. Rear number plate	Refit	70.00		--	
Total For Parts :-		3,504.00		1,531.36	
Labour Charges :					
Labour charges to panel beating, straighten and realign all affected areas. To remove, check, reinstall and replace parts.		900.00		450 500.00	
Check wiring and lighting system for proper function.		70.00		30.00	

Vehicle No : SLK 4432 K Honda Civic (A)
 Workshop : Empire Image Pte Ltd

TP/0007/21

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
Spray anti rust chemical to repaired and replaced panels.		70.00		30.00	
Remove and reinstall rear inner garnish and trim to facilitate repairs.		250.00		120.00	60
Remove, check, replace and reinstall rear bumper reverse sensors and wire harness to facilitate repairs.		100.00		40.00	
Spray Painting :					
Putty and spray repaired and replaced dy panels.		1,000.00		750.00	700
Grand Total :-		5,894.00		3,001.36	

Surveyed By : Lawrence Ng

1414.71
 480.00
 830.00

2724.71
 20%
 2179.77

L/S-\$2,150/4 DAYS