

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21013063/KQY3E2

Date: 26/05/2022

REFERENCE

Insured/Claimant: ONG KAY SOON LIGHTZ Policy No: DMPCSNW00190802100

Date of Loss: 18/12/2021

Nature of Claim: OD

Claim No: SNM21D207446/C01/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNB8727H**

Make & Model: TOYOTA YARIS CROSS, 1.5 X B-PKG CVT (A)

Engine No: M15AY181561

Reg. Date: 17/09/2021 (Man. Year: 2021)

Chassis No: MXPB102010218

Colour: Metallic Red

Odometer: 3621 km

Engine Capacity: 1490 cc

Market Value/New Car Price: S\$102,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16

Rear Tyre Size: 205/65 R16

Front Left Side: Bridgestone 9 mm

Rear Left Side: Bridgestone 9 mm

Front Right Side: Bridgestone 9 mm

Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,560.00	4,420.00	3,140.00	41.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	630.20	355.00	275.20	43.67
Paintwork Labour	140.66	109.56	31.10	22.11
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,330.86	4,884.56	3,446.30	41.37
+ GST 7.00/7.00% (S\$)	583.16	341.92	241.24	41.37
Nett Amount (S\$)	8,914.02	5,226.48	3,687.54	41.37

INSPECTION

Date of Assignment: 22/12/2021 Present Location:

Ding Auto Pte Ltd (HQ)

Date Inspected: 28/12/2021 Inspected At:

Ding Auto Pte Ltd (HQ)

176 Sin Ming Drive #04-06, Sin Ming Autocare

Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2022)
Parts:	M1-SUV	TOYOTA YARIS CROSS 1.5 X B-PKG CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB8727H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		7,310.00 F	*4,170.00 F
<u>Supplementary #1</u>						
2	1		*FRONT BUMPER LOWER GARNISH	Mtg Cracked	250.00 F	*250.00 F
F=Franchise part.						
Total Parts (S\$)					7,560.00	4,420.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	75.60	63.00
2	Total Paint Materials	New	65.06	46.56
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	130.20	105.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
4	RADAR SENSOR - RESETTING	New	500.00	250.00
Gross Labour Cost (\$\$)			770.86	464.56

Report was unsubmitted during this print-out.

< END OF ESTIMATES >