

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013070/GNY3E2**Date:** 31/03/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00054652100

**Claimant Vehicle
No :** SJP863Z**Insured Vehicle
No :** SDK122B

Date of Loss: 21/12/2021

Nature of Claim: TP

Claim
No: SNM21D207460/C02/TANKWDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJP863Z**

Make & Model: NISSAN SYLPHY, 1.6 (A)

Engine No: HR16937222C

Reg. Date: 17/12/2018 (Man. Year: 2018)

Chassis No: MNTBBAB17Z0033851

Colour: Brown

Odometer: 36178 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16

Rear Tyre Size: 195/60 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,616.80	3,642.70	20,974.10	85.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,650.00	1,940.00	5,710.00	74.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,266.80	5,582.70	26,684.10	82.70
Approved Total (Overridden) (S\$)		4,400.00		
Nett Amount (S\$)	32,266.80	4,400.00	27,866.80	86.36

INSPECTION

Date of Assignment: 27/12/2021

Date Inspected: 23/12/2021 Inspected At:

JEW Motors (HQ)
60 Jalan Lam Huat Carros Centre #03-72
Singapore 737869

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Mar 2023)
Parts:	143	NISSAN SYLPHY 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP863Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Not Necessary	1,347.00 FL	*- FL
2	1		*HEADLAMP BRACKET RH	Not Necessary	75.00 FL	*- FL
3	1		*FRONT BUMPER	Not Necessary	589.00 FL	*- FL
4	1		*FRONT BUMPER RETAINER RH	Not Necessary	45.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	273.00 FL	*- FL
6	1		*FRONT BUMPER SPONGE	Not Necessary	279.00 FL	*- FL
7	1		*FRONT BUMPER UNDERCOVER	Not Necessary	213.00 FL	*- FL
8	1		*FRONT FENDER RH	Not Necessary	689.00 FL	*- FL
9	1		*FRONT FENDER COWLING RH	Not Necessary	262.00 FL	*- FL
10	1		*FRONT DOOR RH	Buckled	1,225.00 FL	*1,225.00 FL
11	1		*FRONT DOOR SIDE MIRROR ASSY RH	Repair	267.00 FL	*- FL
12	1		*FRONT DOOR SIDE MIRROR COVER RH	Repair	69.00 FL	*- FL
13	1		*FRONT DOOR WINDOW MOULDING RH	Not Necessary	148.00 FL	*- FL
14	1		*FRONT DOOR LOCK RH	Jammed	228.00 FL	*228.00 FL
15	1		*FRONT DOOR LOCK CATCH RH	Not Necessary	47.00 FL	*- FL
16	1		*FRONT DOOR POWER WINDOW MOTOR RH	Not Necessary	436.00 FL	*- FL
17	1		*FRONT DOOR WINDOW REGULATOR RH	Bent	76.00 FL	*76.00 FL
18	1		*FRONT DOOR SPEAKER RH (NPA)	Not Necessary	0.00 FL	*- FL
19	2		*FRONT DOOR HINGE RH	Not Necessary	90.00 FL	*- FL
20	1		*FRONT DOOR CHECKER RH	Not Necessary	40.00 FL	*- FL
21	1		*FRONT DOOR WEATHERSTRIP RH	Torn	95.00 FL	*95.00 FL
22	1		*FRONT DOOR INNER WEATHERSTRIP RH	Not Necessary	62.00 FL	*- FL
23	1		*REAR DOOR RH	Bent	1,016.00 FL	*1,016.00 FL
24	1		*REAR DOOR LOCK RH	Not Necessary	228.00 FL	*- FL
25	1		*REAR DOOR LOCK CATCH RH	Not Necessary	47.00 FL	*- FL
26	1		*REAR DOOR INNER BOARD RH	Not Necessary	306.00 FL	*- FL
27	1		*REAR DOOR WINDOW REGULATOR RH	Bent	76.00 FL	*76.00 FL
28	2		*REAR DOOR HINGE RH	Not Necessary	90.00 FL	*- FL
29	1		*REAR DOOR CHECKER RH	Not Necessary	40.00 FL	*- FL
30	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	95.00 FL	*- FL
31	1		*REAR DOOR INNER WEATHERSTRIP RH	Not Necessary	62.00 FL	*- FL
32	1		*ROCKER PANEL RH	Repair	1,125.00 FL	*- FL
33	1		*REAR FENDER RH	Not Necessary	1,154.00 FL	*- FL
34	1		*REAR FENDER COWLING RH	Not Necessary	212.00 FL	*- FL
35	1		*TAIL LAMP RH	Not Necessary	367.00 FL	*- FL
36	1		*REAR BUMPER	Broken	681.00 FL	*681.00 FL
37	1		*REAR BUMPER RETAINER RH	Not Necessary	69.00 FL	*- FL
38	1		*FRONT ABSORBER RH	Not Necessary	485.00 FL	*- FL
39	1		*FRONT LOWER ARM RH	Not Necessary	207.00 FL	*- FL
40	1		*FRONT KNUCKLE RH	Not Necessary	589.00 FL	*- FL
41	1		*FRONT KNUCKLE BEARING RH	Not Necessary	371.00 FL	*- FL
42	1		*FRONT BEARING HUB RH	Not Necessary	265.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT TIE ROD RH	Not Necessary	77.00 FL	*- FL
44	1		*FRONT TIE ROD END RH	Not Necessary	45.00 FL	*- FL
45	1		*FRONT STABILIZER LINK RH	Not Necessary	125.00 FL	*- FL
46	1		*REAR ABSORBER RH	Not Necessary	172.00 FL	*- FL
47	1		*REAR KNUCKLE BEARING WITH HUB RH	Not Necessary	415.00 FL	*- FL
48	1		*REAR AXLE	Not Necessary	1,736.00 FL	*- FL
49	1		*REAR DOOR POWER WINDOW MOTOR RH	Not Necessary	436.00 FL	*- FL
50	1		*FRONT BUMPER CLIPS	Not Necessary	100.00 FS	*- FS
51	1		*FRONT FENDER CLIPS	Not Necessary	100.00 FS	*- FS
52	1		*FRONT FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
53	1		*FRONT DOOR INNER BOARD CLIPS	Necessary	100.00 FS	*30.00 FS
54	1		*REAR DOOR INNER BOARD CLIPS	Necessary	100.00 FS	*30.00 FS
55	1		*B PILLAR SEALANT	Not Necessary	80.00 FS	*- FS
56	1		*B PILLAR INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
57	1		*ROCKER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
58	1		*REAR FENDER SEALANT	Not Necessary	150.00 FS	*- FS
59	1		*REAR FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
60	1		*REAR BUMPER CLIPS	Not Necessary	100.00 FS	*- FS
61	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
62	1		*FRONT RIM RH	Not Necessary	3,500.00 FS	*- FS
63	1		*FRONT TYRE RH	Not Necessary	400.00 FS	*- FS
64	1		*REAR RIM RH	Scratched	3,500.00 FS	*250.00 FS
65	1		*REAR TYRE RH	Not Necessary	400.00 FS	*- FS
66	1		*FRONT DOOR INNER BOARD RH	Broken	306.00 FL	*306.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	26,352.00	4,013.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,735.20	370.30
Total Parts (\$)	24,616.80	3,642.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,600.00	600.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,800.00	1,000.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	New	150.00	0.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	0.00
5	TO RNR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
6	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	200.00	60.00
7	TO RNR UNDERCARRIAGE	New	250.00	50.00
8	TO CHECK WHEEL BALANCING	New	200.00	0.00
9	TO CHECK WATER LEAK	New	150.00	0.00
10	TO RNR FUEL TANK	New	300.00	0.00
11	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
12	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	0.00
13	TO RNR REAR AND FRONT DOOR MECHANISM	New	500.00	120.00
14	TO PERFORM RUST PROOFING	New	200.00	50.00
Gross Labour Cost (S\$)			7,650.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >