

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013073/DQY3N2**Date:** 25/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00004242101
Claimant Vehicle No :	SMP2467K	Insured Vehicle No :	SKQ7732E
Date of Loss:	21/12/2021	Nature of Claim:	TP
		Claim No:	SNM21D207486/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP2467K	Engine No:	2ZR0E00484
Make & Model:	TOYOTA NOAH HYBRID, 1.8 (A)	Chassis No:	ZWR800396029
Reg. Date:	18/09/2019 (Man. Year: 2019)	Odometer:	166466 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,342.92	5,630.16	20,712.76	78.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,420.00	1,890.00	5,530.00	74.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	33,762.92	7,520.16	26,242.76	77.73
Approved Total (Overridden) (\$\$)		6,000.00		
(\$\$)	33,762.92	6,000.00	27,762.92	82.23
+ GST 7.00/7.00% (\$\$)	2,363.40	420.00	1,943.40	82.23
Nett Amount (\$\$)	36,126.32	6,420.00	29,706.32	82.23

INSPECTION

Date of Assignment:	23/12/2021	
Date Inspected:	23/12/2021 Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A., #03-08 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 May 2022)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP2467K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	2,406.10 FL	*1,645.10 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	407.20 FL	*185.00 FL
3	1		*TAILGATE CHROME MOULDING	Not Necessary	988.20 FL	*- FL
4	1		*TAILGATE TOYOTA LOGO	Not Necessary	58.80 FL	*- FL
5	2		*TAILGATE NO PLATE LAMP L+R	Not Necessary	215.36 FL	*- FL
6	1		*TAILGATE INNER TRIM BOARD	Mtg Broken	993.70 FL	*425.00 FL
7	1		*TAILGATE WEATHERSTRIP	Deformed / Necessary	725.50 FL	*277.00 FL
8	1		*TAILGATE LOCK	Damaged	461.50 FL	*461.50 FL
9	1		*TAILGATE HYBRID EMBLEM	Necessary	62.15 FL	*62.15 FL
10	1		*REAR BUMPER	Dented	1,491.90 FL	*798.20 FL
11	2		*REAR BUMPER SIDE RETAINER L+R	Serviceable	259.80 FL	*- FL
12	2		*REAR BUMPER BRACKET L+R	Not Necessary	176.78 FL	*- FL
13	2		*REAR BUMPER REFLECTOR L+R	Not Necessary	211.60 FL	*- FL
14	1		*REAR BUMPER TOW HOOK COVER	Cut / Distorted	51.80 FL	*51.80 FL
15	1		*REAR END PANEL INNER	Repair	1,405.90 FL	*- FL
16	1		*REAR END PANEL OUTER	Dented	1,720.85 FL	*685.10 FL
17	1		*REAR END PANEL TOP GARNISH	Mtg Deformed	323.00 FL	*204.50 FL
18	1		*REAR FLOOR PANEL	Not Necessary	1,876.20 FL	*- FL
19	1		*REAR FLOOR PANEL TOP BOARD	Bent	1,009.20 FL	*691.00 FL
20	2		*REAR FENDER LH/RH	Not Necessary	5,971.40 FL	*- FL
21	2		*REAR FENDER INNER TRIM BOARD L+R	Cracked / Broken	2,936.96 FL	*1,362.20 FL
22	2		*REAR FENDER QUARTER GLASS MOULDING	Not Necessary	999.60 FL	*- FL
23	2		*TAIL LAMP L+R	Not Necessary	3,379.70 FL	*- FL
24	2		*TAIL LAMP LOWER BRACKET L+R	Not Necessary	348.50 FL	*- FL
25	2		*TAIL LAMP PANEL L+R	Not Necessary	1,796.00 FL	*- FL
26	2		*TAIL LAMP LOWER GARNISH LH/RH	Not Necessary	997.50 FL	*- FL
27	1		*REAR EXHAUST PIPE	Not Necessary	1,473.90 FL	*- FL
28	1		*REAR EXHAUST MOUNTING	Not Necessary	288.80 FL	*- FL
29	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	355.00 FL	*- FL
30	1		*REAR KEYLESS SENSOR	Mtg Broken	291.00 FL	*165.00 FL
31	1		*SET REAR REVERSE SENSOR	Damaged	300.00 FS	*220.00 FS
32	1		*REAR NO PLATE & GARNISH	Not Necessary	100.00 FS	*- FS
33	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
34	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
35	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
36	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
37	1		*REAR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
38	1		*TAIL LAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
39	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
40	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
41	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS
42	1		*REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*20.00 FS
43	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **34,763.90** **7,383.55**
- List Item Discount on L Items 25.00/25.00% (\$\$) 8,420.98 1,753.39

Report was unsubmitted during this print-out.

5/25/22, 11:31 AM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	26,342.92
						5,630.16
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	700.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	700.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR SLIDING DOOR TO FACILITATE REPAIRS	New	300.00	0.00
6	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	300.00	0.00
7	TO RNR REVERSE CAMERA	New	100.00	0.00
8	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	250.00	120.00
9	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
10	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
11	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
12	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
13	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	New	120.00	40.00
Gross Labour Cost (\$\$)			7,420.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >