

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21013079/GTF3E2

Date: 09/05/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001726052		
Claimant Vehicle No :	FBL1284D	Insured Vehicle No :	GBG1661A		
Date of Loss:	10/12/2021	Nature of Claim:	TP	Claim No:	266906

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL1284D	Engine No:	M812M1008513
Make & Model:	PIAGGIO VESPA PRIMAVERA, 155cc 150 ABS	Chassis No:	ZAPM8120000005397
Reg. Date:	06/06/2016 (Man. Year: 2015)	Odometer:	0 km
Colour:	White		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70-11	Rear Tyre Size:	120/70-11
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,571.01	1,844.97	3,726.04	66.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	800.00	800.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,171.01	2,644.97	4,526.04	63.12
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	7,171.01	2,000.00	5,171.01	72.11
+ GST 7.00/7.00% (S\$)	501.97	140.00	361.97	72.11
Nett Amount (S\$)	7,672.98	2,140.00	5,532.98	72.11

INSPECTION

Date of Assignment:	23/12/2021	
Date Inspected:	24/12/2021	Inspected At: Yew Tee Automobile Tech Pte Ltd (HQ) Blk 6 Woodlands Road 399F,, Yew Tee Ind Estate Singapore 678006
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Apr 2022)	
Parts:	N/A	PIAGGIO VESPA PRIMAVERA 155cc 150 ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL1284D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TRANSMISSION COVER	Cut	467.75 FL	*375.00 FL
2	1		*COOLING COVER	Broken	88.10 FL	*48.00 FL
3	1		*REAR LEFT PANEL	Repair	531.60 FL	*- FL
4	1		*REAR LEFT FOOT REST	Bent	383.10 FL	*105.00 FL
5	1		*REAR LEFT FOOT REST BRACKET	Bent	234.60 FL	*45.00 FL
6	1		*REAR RIGHT FOOT REST	Cut	383.10 FL	*105.00 FL
7	1		*REAR RIGHT FOOT REST BRACKET	Cut	234.60 FL	*45.00 FL
8	1		*REAR RIGHT PANEL	Repair	861.30 FL	*- FL
9	1		*STEP PANEL TOP GARNISH RH	Cut	415.80 FL	*68.00 FL
10	1		*STEP PANEL RH	Cracked	564.30 FL	*564.30 FL
11	1		*STEP PANEL CHROME RH	Cut	282.10 FL	*70.00 FL
12	1		*EXHAUST COVER	Cut	445.50 FL	*90.00 FL
13	1		*STEP PANEL END RH	Cracked	297.50 FL	*45.00 FL
14	1		*SIDE MIRROR RH	Cut	178.20 FL	*85.00 FL
15	1		*BRAKE LEVER	Cut	62.30 FL	*18.00 FL
16	1		*FRONT FENDER	Cut	393.50 FL	*160.00 FL
17	1		*VESPA EMBLEM	Necessary	80.00 FS	*48.00 FS
18	1		*IU UNIT	Cut	250.00 FS	*156.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,153.35	2,027.30
- List Item Discount on L Items 10.00/10.00% (\$)	582.34	182.33
Total Parts (\$)	5,571.01	1,844.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,000.00	400.00
2	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	600.00	400.00
Gross Labour Cost (\$\$)			1,600.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >