

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013081/BQY3N2**Date:** 01/06/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00044192100
Claimant Vehicle No :	SLS5847Z	Insured Vehicle No :	SJP1603B
Date of Loss:	08/12/2021	Nature of Claim:	TP
		Claim No:	SNM21D207164/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS5847Z		
Make & Model:	CITROEN DS4 CROSSBACK, 1.6 BLUEHDI S&S EAT6 (A)	Engine No:	10JBHX3016887
Reg. Date:	28/09/2017 (Man. Year: 2016)	Chassis No:	VF7NXBHZTGY555835
Colour:	White	Odometer:	80153 km
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,791.73	5,717.27	8,074.46	58.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,540.00	1,410.00	47.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,741.73	7,257.27	9,484.46	56.65
Approved Total (Overridden) (\$\$)		5,750.00		
(\$\$)	16,741.73	5,750.00	10,991.73	65.65
+ GST 7.00/7.00% (\$\$)	1,171.92	402.50	769.42	65.65
Nett Amount (\$\$)	17,913.65	6,152.50	11,761.15	65.65

INSPECTION

Date of Assignment:	16/04/2022	
Date Inspected:	24/12/2021	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Jun 2022)

Parts: 143 CITROEN DS4 CROSSBACK 1.6 BLUEHDI S&S EAT6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLS5847Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Dented	2,050.33 FL	*1,485.00 FL
2	1	*TAILGATE WINDSCREEN GLASS WITH RUBBER MOULDING	Not Necessary	1,278.30 FL	*- FL
3	1	*TAILGATE CENTRE EMBLEM	Necessary	139.79 FL	*82.00 FL
4	1	*TAILGATE CROSSBACK EMBLEM	Necessary	203.45 FL	*97.50 FL
5	1	*TAILGATE DS4 EMBLEM	Necessary	89.67 FL	*89.67 FL
6	1	*TAILGATE BLUEHDI EMBLEM	Necessary	128.56 FL	*97.40 FL
7	1	*TAILGATE LOCK	Not Damaged	239.88 FL	*- FL
8	1	*TAILGATE INNER TRIM BOARD	Not Damaged	500.78 FL	*- FL
9	1	*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	70.00 FL	*- FL
10	1	*TAILGATE WEATHERSTRIP	Not Damaged	288.21 FL	*- FL
11	1	*REAR BUMPER	Broken	1,489.67 FL	*1,489.67 FL
12	1	*SET REAR BUMPER CLIPS	Necessary	75.00 FL	*30.00 FL
13	1	*REAR BUMPER LOWER GARNISH	Broken	550.78 FL	*550.78 FL
14	1	*REAR BUMPER LOWER RH GARNISH	Broken	301.12 FL	*301.12 FL
15	1	*REAR BUMPER LOWER RH GARNISH	Broken	301.12 FL	*301.12 FL
16	1	*REAR BUMPER CHROME GARNISH	Broken	333.47 FL	*333.47 FL
17	1	*REAR BUMPER RH SIDE REVERSE SENSOR	Not Necessary	308.44 FL	*- FL
18	1	*REAR BUMPER LH SIDE REVERSE SENSOR	Not Necessary	308.44 FL	*- FL
19	4	*REAR BUMPER REVERSE SENSOR HOLDERS	Necessary	81.20 FL	*60.00 FL
20	1	*REAR BUMPER RH SIDE BRACKET	Not Damaged	189.89 FL	*- FL
21	1	*REAR BUMPER LH SIDE BRACKET	Not Damaged	189.89 FL	*- FL
22	1	*REAR BUMPER REINFORCEMENT	Not Damaged	533.38 FL	*- FL
23	1	*REAR BUMPER RH SIDE RETAINER	Necessary	94.57 FL	*94.57 FL
24	1	*REAR BUMPER LH SIDE RETAINER	Necessary	94.57 FL	*94.57 FL
25	1	*END PANEL	Repair	899.56 FL	*- FL
26	1	*END PANEL INNER GARNISH	Not Necessary	233.10 FL	*- FL
27	1	*SET END PANEL INNER GARNISH CLIPS	Not Necessary	50.00 FL	*- FL
28	1	*RH TAILLAMP	Not Damaged	713.45 FL	*- FL
29	1	*LH TAILLAMP	Not Damaged	713.45 FL	*- FL
30	1	*SET REAR FENDER RH INNER TRIM BOARD CLIPS	Not Necessary	60.00 FL	*- FL
31	1	*SET REAR FENDER LH INNER TRIM BOARD CLIPS	Not Necessary	60.00 FL	*- FL
32	1	*EXHAUST SILENCER	Dented	1,782.10 FL	*885.00 FL
33	1	*EXHAUST SILENCER GASKET	Necessary	55.10 FL	*55.10 FL
34	1	*REAR BUMPER RH CENTRE REVERSE SENSOR }	Short Circuit	308.44 FL	*200.00 FL
35	1	*REAR BUMPER LH CENTRE REVERSE SENSOR }	Short Circuit	308.44 FL	*- FL
36	1	*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
37	1	*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*20.00 FS
38	1	*TAILGATE C&C EMBLEM	Necessary	80.00 FS	*45.00 FS
39	1	*END PANEL JOINT SEALANT	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,294.15	6,341.97
- List Item Discount on L Items 10.00/10.00% (\$)	1,502.42	624.70
Total Parts (\$)	13,791.73	5,717.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS,TO PANEL BEATING.CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	600.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	80.00	0.00
5	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS TO ASSIST REPAIR	New	200.00	120.00
6	REMOVE AND REPLACE TAILGATE INNER MECHANISM TO ASSIST REPAIR	New	120.00	80.00
7	REMOVE AND REPLACE REAR INNER TRIMS AND BOARDS TO ASSIST REPAIR	New	200.00	0.00
8	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	120.00	60.00
9	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	150.00	80.00
Gross Labour Cost (\$)			2,950.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >