

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013082/EQY3N2**Date:** 28/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00110712100

Claimant Vehicle No : SJS1825L **Insured Vehicle No :** XD7622D

Date of Loss: 16/12/2021 Nature of Claim: TP Claim No: SNM21D207452/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS1825L**

Make & Model: HONDA CIVIC, 1.5 (A) Engine No: R18A14011322

Reg. Date: 31/07/2009 (Man. Year: 2008) Chassis No: JHMFD16309S201933

Colour: Black Odometer: 144600 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	805.76	792.16	13.60	1.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	630.00	250.00	28.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	1,685.76	1,422.16	263.60	15.64
Approved Total (Overridden) (\$\$)		1,150.00		
(\$\$)	1,685.76	1,150.00	535.76	31.78
+ GST 7.00/7.00% (\$\$)	118.00	80.50	37.50	31.78
Nett Amount (\$\$)	1,803.76	1,230.50	573.26	31.78

INSPECTION

Date of Assignment: 23/12/2021

Date Inspected: 12/01/2022 Inspected At: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Blk 3 Pioneer Road North, #01-18
Singapore 628457

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2022)
Parts:	143	HONDA CIVIC 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS1825L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	638.00 FL	*638.00 FL
2	1		*REAR BUMPER RETAINER LH	Broken	20.90 FL	*20.90 FL
3	1		*REAR BUMPER UPP SIDE BRACKET LH	Not Necessary	17.00 FL	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	37.00 FL	*37.00 FL
5	1		*REAR TAILLAMP LH	Cracked	294.30 FL	*294.30 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	1,007.20 990.20
					- List Item Discount on L Items 20.00/20.00% (S\$)	201.44 198.04
					Total Parts (S\$)	805.76 792.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK RR FENDER LH,WELD,REMOVE & FIX ON ABOVE PARTS	New	400.00	200.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	450.00	400.00
3	TO CHECK WIRING	New	30.00	30.00
Gross Labour Cost (\$)			880.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >