

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG21013092/GVY3M4
Date: 09/09/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28758454
Claimant Vehicle No : FBK7990P Insured Vehicle No : GBD8605H
Date of Loss: 21/03/2019 Nature of Claim: TP Claim No: 588499

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBK7990P**
Make & Model: KAWASAKI ZG1400C, 1.4 Engine No: ZXT40AE073607
Reg. Date: 31/01/2013 (Man. Year: 2012) Chassis No: JKBZGT40CCA020793
Colour: Grey Odometer: 0 km
Engine Capacity: 1352 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 ZR17 Rear Tyre Size: 120/70 ZR17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/12/2021
Date Inspected: 24/12/2021 Inspected At: M2 Garage Pte Ltd (HQ)
61 WOODLANDS INDUSTRIAL PARK E9 PREMIER 9S
(01-17)
Singapore 757047
Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00
-\$5,000.00

Notes: The vehicle had completed its repair works at the time of inspection.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 Sep 2022)	
Parts:	N/A	KAWASAKI ZG1400C 1.4 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/FBK7990P/09/09/2022 10:18	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

LKK Auto Consultants Pte Ltd/FBK7990P/09/09/2022 10:18. Not valid without Reference section.
--

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

LKK Auto Consultants Pte Ltd/FBK7990P/09/09/2022 10:18. Not valid without Reference section.
--

< END OF ESTIMATES >