

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21013093/KTY3E2

**Date:** 31/03/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00195392100  
**Claimant Vehicle No :** SLR2244M **Insured Vehicle No :** SKV8285X  
Date of Loss: 21/12/2021 Nature of Claim: TP Claim No: SNM21D207492/C02/CSC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR2244M**  
Make & Model: HONDA HR-V, 1.5 (A) Engine No: L15B4532553  
Reg. Date: 04/08/2017 (Man. Year: 2017) Chassis No: JHMRU1830GX202553  
Colour: Metallic Grey Odometer: 54705 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
Front Left Side: Dunlop 3 mm Rear Left Side: Dunlop 3 mm  
Front Right Side: Dunlop 3 mm Rear Right Side: Dunlop 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,916.96	1,588.48	328.48	17.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,570.00	1,090.00	480.00	30.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,486.96</b>	<b>2,678.48</b>	<b>808.48</b>	<b>23.19</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,150.00</b>		
<b>(S\$)</b>	3,486.96	2,150.00	1,336.96	38.34
<b>+ GST 7.00/7.00% (S\$)</b>	244.09	150.50	93.59	38.34
<b>Nett Amount (S\$)</b>	<b>3,731.05</b>	<b>2,300.50</b>	<b>1,430.55</b>	<b>38.34</b>

### INSPECTION

Date of Assignment: 17/03/2022  
Date Inspected: 30/12/2021 Inspected At: Falcon Air Auto Services Pte Ltd (HQ)  
176 Sin Ming Drive #01-06, Sin Ming Autocare  
Singapore 575721  
Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Mar 2022)
Parts:	M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR2244M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH REAR DOOR	Bent	960.90 FL	*960.90 FL
2	1		*LH REAR DOOR BLACK TAPE	Necessary	21.00 FL	*21.00 FL
3	1		*LH REAR DOOR STONE GUARD	Necessary	25.70 FL	*25.70 FL
4	1		*LH SIDE SKIRT	Repair	410.60 FL	*- FL
5	1		*LH SIDE SKIRT STONE GUARD	Necessary	25.00 FL	*25.00 FL
6	1		*REAR WHEEL ARCH GARNISH	Dented / Cut	187.20 FL	*187.20 FL
7	1		*LH REAR SPORTS RIM - R16	Dented	765.80 FL	*765.80 FL
					Sub Total (\$\$)	2,396.20 1,985.60
					- List Item Discount on L Items 20.00/20.00% (\$\$)	479.24 397.12
					Total Parts (\$\$)	1,916.96 1,588.48

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	COMPUTERISE WHEEL ALIGNMENT	New	120.00	60.00
2	TO TRANSFER TYRE TO NEW RIM AND BALANCING	New	50.00	20.00
3	TO TRANSFER DOOR MECHANISM	New	100.00	60.00
4	TO REPAIR LH REAR ARCH PANEL INCLUDING REPLACEMENT OF PARTS	New	600.00	400.00
5	TO SPRAY PAINT ON LH SIDE SKIRT, LH SIDE REAR ARCH PANEL, LH REAR DOOR, LH REAR ARCH GARNISH	New	700.00	550.00
<b>Gross Labour Cost (\$)</b>			<b>1,570.00</b>	<b>1,090.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >