

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013097/VTY3N2**Date:** 09/02/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00049482100

Claimant Vehicle No : SJA53Z **Insured Vehicle No :** GBJ3596B

Date of Loss: 23/12/2021 Nature of Claim: TP Claim No: SNM21D207539/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJA53Z**

Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZX556853

Reg. Date: 02/07/2007 (Man. Year: 2007) Chassis No: MR053HY9305004830

Colour: Black Odometer: 275626 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,932.00	3,271.14	660.86	16.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,870.00	1,940.00	1,930.00	49.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,802.00	5,211.14	2,590.86	33.21
Approved Total (Overridden) (S\$)		3,650.00		
(S\$)	7,802.00	3,650.00	4,152.00	53.22
+ GST 7.00/7.00% (S\$)	546.14	255.50	290.64	53.22
Nett Amount (S\$)	8,348.14	3,905.50	4,442.64	53.22

INSPECTION

Date of Assignment: 27/01/2022

Date Inspected: 04/01/2022 Inspected At: Premier Automotive Services Pte Ltd (HQ)
23 Changi South Ave 2, #01-02
Singapore 486443

Estimated Period of Repair: 5.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Feb 2022)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJA53Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	790.00 FL	*790.00 FL
2	1		*REAR BOOTLID HINGE RH	Serviceable	48.00 FL	*- FL
3	1		*REAR BOOTLID HINGE LH	Serviceable	48.00 FL	*- FL
4	1		*REAR BOOTLID LOGO	Necessary	50.00 FL	*50.00 FL
5	1		*REAR BOOTLID EMBLEM (VIOS)	Necessary	44.00 FL	*44.00 FL
6	1		*REAR BOOTLID EMBLEM (J)	Necessary	35.00 FL	*35.00 FL
7	1		*REAR BOOTLID LOCK	Jammed	95.00 FL	*95.00 FL
8	1		*REAR BOOTLID RUBBER	Cut	185.00 FL	*185.00 FL
9	1		*REAR LAMP RH	Cracked	380.00 FL	*380.00 FL
10	1		*REAR LAMP LH	Cracked	380.00 FL	*380.00 FL
11	6		*REAR LAMP CLIPS	Necessary	24.00 FL	*24.00 FL
12	1		*REAR BUMPER	Dented	600.00 FL	*520.56 FL
13	1		*REAR BUMPER SIDE RETAINER RH	Necessary	89.00 FL	*89.00 FL
14	1		*REAR BUMPER SIDE RETAINER RH	Necessary	89.00 FL	*89.00 FL
15	1		*REAR BUMPER INNER BRACKET RH	Necessary	38.00 FL	*38.00 FL
16	1		*REAR BUMPER INNER BRACKET LH	Necessary	38.00 FL	*38.00 FL
17	1		*REAR END PANEL	Dented	780.00 FL	*590.00 FL
18	1		*REAR END PANEL TOP GARNISH	Cut	200.00 FL	*165.80 FL
19	1		*SPARE TYRE BOARD	Cut	120.00 FL	*120.00 FL
20	1		*TAIL LAMP PANEL RH	Dented	89.00 FL	*89.00 FL
21	1		*TAIL LAMP PANEL LH	Dented	89.00 FL	*89.00 FL
22	1		*REAR BUMPER LOWER REFLECTOR RH	Cracked	105.00 FL	*58.00 FL
23	1		*REAR BUMPER LOWER REFLECTOR LH	Cracked	105.00 FL	*58.00 FL
24	1		*BOOTLID CENTRE MOULDING	Bent	115.00 FL	*57.50 FL
25	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
26	1		*REAR FENDER LH (NPA)	Repair	0.00 FL	*- FL
27	1		*SPARE TYRE PANEL (NPA)	Repair	0.00 FL	*- FL
28	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	50.00 FS	*- FS
29	1		*SET END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
30	1		*SET REVERSE SENSOR	Cut	250.00 FS	*200.00 FS
31	1		*SUNDRY	Serviceable	50.00 FS	*- FS
32	1		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
33	1		*REAR END PANEL BRACKET RH	Serviceable	65.00 FL	*- FL
34	1		*REAR END PANEL BRACKET LH	Serviceable	65.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,106.00	4,274.86
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,174.00	1,003.72
Total Parts (\$\$)	3,932.00	3,271.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	40.00	20.00
2	TO DISMANTLE AND REPLACE NEW REVERSE SENSOR AND RESET TO THE SAME	New	80.00	20.00
3	TO DISMANTLE/REFIT THE INNER GARNISH,INNER LINING,INNER TRIM,CUSHION SEAT,ETC TO FACILITATE REPAIR	New	200.00	70.00
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.TO HEAT/WELD,CUT-OFF THE END PANEL,FLOORBOARD COMPARTMENT,REAR O/S TAIL LAMP PANEL,REAR N/S TAIL LAMP PANEL.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE REAR O/S & N/S FENDER,ETC	New	1,800.00	900.00
5	TO PUTTY AND SPRAY PAINTING ON THE BOOTLID,REAR BUMPER,END PANEL,FLOORBOARD COMPARTMENT,N/S & O/S TAILLAMP PANEL,REAR O/S & N/S FENDER,REAR O/S & N/S CORNER PANEL	New	1,600.00	900.00
6	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	150.00	30.00
Gross Labour Cost (\$\$)			3,870.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >