



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 911Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT FORK ASSY	SERVICEABLE	980.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	190.00	-
1	HEADLAMP	SERVICEABLE	550.00	-
1	O/S SIDE MIRROR	CUT	120.00	60.00
1	HANDLE-BAR	SERVICEABLE	135.00	-
1	O/S HANDLE-BAR BALANCER	SCRATCHED	80.00	30.00
1	SET HANDLE GRIP	NOT NECESSARY	60.00	-
2	BRAKE LEVER	O/S SCRATCHED	104.00	45.00
2	FOOTSTEP PANEL	O/S CUT / N/S NOT NECESSARY	510.00	145.00
2	FOOTSTEP PANEL LOWER COVER	O/S CUT / N/S NOT NECESSARY	340.00	140.00
1	SET FAIRING COVER	DAMAGED	1,350.00	850.00
1	EXHAUST ASSY	BENT	680.00	535.00
1	EXHAUST BRACKET	CRACKED	280.00	225.00
1	EXHAUST PROTECTOR	CUT	98.00	98.00
1	ENGINE MOUNTING	BENT	480.00	410.00
1	REAR MUDGUARD	MISSING	168.00	140.00
1	REAR SIGNAL	BROKEN	180.00	68.00
1	REAR SIGNAL COVER - MATT	CUT	180.00	180.00
1	REAR NUMBER PLATE LAMP	NOT NECESSARY	128.00	-
1	REAR TAIL LAMP	NOT NECESSARY	280.00	-
1	REAR ABSORBER	BENT / TWISTED	650.00	450.00
1	REAR RIM	CUT / WARPED	680.00	350.00
1	RADIATOR COVER	CUT	155.00	105.00
	LESS 10% DISCOUNT		-837.80	-383.10
			7,540.20	3,447.90
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET NUMBER PLATE (SN)	REAR MISSING	38.00	14.00
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-

Report Ref No. CS/UOI21013098/Uvf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET STEERING CONE (SN)	NOT NECESSARY	120.00	-
1	REAR BOX BRACKET (SN)	TO REPAIR SEE LABOUR	180.00	-
1	REAR TYRE (SN)	SERVICEABLE	280.00	-
1	"AEROX" EMBLEM (SN)	NECESSARY	60.00	60.00
			764.00	74.00
	<b>LABOUR</b>			
	TO PROVIDE TOWING (LOD).		50.00	50.00
	TO PROVIDE WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	480.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF REAR BOX BRACKET .		450.00	300.00
			1,060.00	350.00
<b>GRAND TOTAL</b>			<b>9,364.20</b>	<b>3,871.90</b>

<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,871.90</b>
------------------------------------	--	--	--	-----------------

Report Ref No. CS/UOI21013098/Uvf3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.