

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21013108/UGA3Q2**Date:** 19/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700019741-04
<b>Claimant Vehicle No :</b>	SLT8393R	<b>Insured Vehicle No :</b>	SLQ3379G
Date of Loss:	24/12/2021	Nature of Claim:	TP
		Claim No:	7428201084SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLT8393R</b>		
Make & Model:	HONDA SHUTTLE, 1.5 G (A)	Engine No:	L15B5005806
Reg. Date:	14/11/2017 (Man. Year: 2017)	Chassis No:	GK81104858
Colour:	Silver	Odometer:	65293 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Powertrac 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Powertrac 6 mm	Rear Right Side:	Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,271.60	3,502.96	3,768.64	51.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	1,000.00	730.00	42.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>9,001.60</b>	<b>4,502.96</b>	<b>4,498.64</b>	<b>49.98</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,600.00</b>		
<b>(\$\$)</b>	9,001.60	3,600.00	5,401.60	60.01
<b>+ GST 7.00/7.00% (\$\$)</b>	630.11	252.00	378.11	60.01
<b>Nett Amount (\$\$)</b>	<b>9,631.71</b>	<b>3,852.00</b>	<b>5,779.71</b>	<b>60.01</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment:	24/12/2021	
Date Inspected:	24/12/2021	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,150.20 F	*862.90 FL
2	1		*FRONT BUMPER BEAM	Dented	425.80 F	*420.80 FL
3	1		*FRONT BUMPER SIDE RETAINER O/S	Cracked	66.50 F	*66.50 FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
5	1		*HEADLAMP LED O/S	Cracked	2,995.30 F	*2,229.30 FL
6	1		*FRONT FENDER O/S	Repair	645.20 F	*- FL
7	1		*FRONT FENDER INNER PANEL O/S	Repair	522.10 F	*- FL
8	1		*FRONT FENDER INNER SHIELD O/S	Torn	266.50 F	*199.20 FL
9	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Necessary	50.00 F	*50.00 FL
10	1		*FRONT SPORT RIM O/S	Cut	1,100.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,271.60	4,278.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	775.74
Total Parts (\$\$)	7,271.60	3,502.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	60.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT	New	100.00	60.00
4	TP RESET & REPROGRAMME SYSTEM	New	120.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	600.00	420.00
6	TO PUTTY & SPRAY PAINTING	New	800.00	500.00
<b>Gross Labour Cost (\$)</b>			<b>1,730.00</b>	<b>1,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >