



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2204667
INV Date 28/07/2022
Reference CC4/LPC21013109/Upa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SKN 355Y
Insured Veh. YP 4451A
Claim No. 21/21/22/VC00/025286
Policy No. Z/21/VC00/112234
Accident Date 23/12/2021
Inspection Date 27/12/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC4/LPC21013109/Upa3q2

Date: 28/07/2022

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM (FOR MANDATE ONLY)

Insured Veh.	YP 4451A	Veh. Inspected	SKN 355Y
Policy No.	Z/21/VC00/112234	Coverage (\$)	0.00
Claim No.	21/21/22/VC00/025286	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	24/12/2021

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALPHARD (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTEGD21H208331789	Colour	WHITE
Odometer	73945 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R17	CONTINENTAL	6 mm
L/H Front Tyre	215/60 R17	CONTINENTAL	6 mm
R/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm
L/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND REAR WINDSCREEN SHATTERED.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/12/2021	Inspection Date	27/12/2021
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
C)FOR MANDATE ONLY.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 355Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
1	COVER ,RR BUMPER (SN)	DENTED / DEFORMED	637.30	637.30
1	R/R BUMPER EXTENSION (SN)	BENT	59.80	59.80
1	R/R SIDE BPR SUPPORT (SN)	BENT	80.70	80.70
1	COVER ,RR BUMPER (SN)	DENTED	206.10	206.10
1	R/RR BUMPER SUPPORT (SN)	BENT	46.70	46.70
10	CLIPS (SN)	NECESSARY	41.00	41.00
1	L/R BPR HOLE COVER (SN)	DEFORMED	15.90	15.90
1	PANEL SUB-ASSY ,BODY (SN)	TO REPAIR SEE LABOUR	1,070.70	-
1	R/REAR BUMPER BRACKET (SN)	NOT NECESSARY	111.10	-
1	PLATE ,BACK DOOR (SN)	NOT NECESSARY	183.40	-
1	REAR BACK DOOR PANEL (SN)	BADLY DENTED	2,120.20	2,120.20
1	RR BACK DOOR W/STRIP (SN)	NOT NECESSARY	412.60	-
1	REAR BACK DOOR GLASS (SN)	SHORTED	1,242.60	1,242.60
1	BOARD ASSY ,BACK (SN)	NOT NECESSARY	710.60	-
1	REAR BACK DR LOCK ASSY (W/PWR D)(SN)	NOT NECESSARY	495.10	-
1	TOYOTA SYMBOL EMBLEM (SN)	NECESSARY	72.20	72.20
1	'ALPHARD' EMBLEM (SN)	NECESSARY	68.70	68.70
1	R/R COMBINATION LENS (SN)	CRACKED	492.50	492.50
1	R/REAR BOOT LENS (SN)	CRACKED	284.80	284.70
1	ANTENNA ELECTRICAL (SN)	NOT NECESSARY	192.20	-
2	SENSOR ,ULTRASONIC (SN)	NOT NECESSARY	785.60	-
1	RETAINER ,ULTRASONIC (SN)	NECESSARY	20.60	20.60
1	RETAINER ,ULTRASONIC (SN)	NECESSARY	25.70	25.70
2	SIKA 182010 SIKA TACK GO (BLA) (SN)	NECESSARY	216.00	216.00
1	SIKA 207 G+P ADHESIVE PRIMER (SN)	NECESSARY	200.00	200.00
1	GARNISH SUB-ASSY (SN) (ADDITIONAL)	CRACKED	2,072.10	2,072.10
1	BLADE RR WIPER (SN) (ADDITIONAL)	MISSING	60.30	60.30
			11,954.50	7,993.10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	DRILL HOLE & INSTALL REAR REVERSE SENSOR .		180.00	180.00
	CHECK LIGHTING & CONDUCT WATER LEAK TEST.		180.00	180.00
	REMOVE & INSTALL REAR COMPARTMENT CARPET GARNISH AND TRIMMING TO ASSIST REPAIR.		360.00	360.00
	SUPPLY SEALANT (NETT)-TAILGATE ,REAR END PANEL.		120.00	60.00
	REPLACE & INSTALL REAR WINDSCREEN GLASS .		462.00	462.00
	INSTALL REAR WINDSCREEN GLASS 3M SOLAR FILM.		350.00	350.00
	TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE.		360.00	360.00
	TO RESET ECU AND REPROGRAMME .		180.00	180.00
	REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY ,BODY.		3,600.00	2,160.00
	RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS.		3,540.00	2,360.00
			9,332.00	6,652.00
	GRAND TOTAL		21,286.50	14,645.10
	RECOMMENDED COST OF REPAIRS			14,645.10

Report Ref No. CC4/LPC21013109/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKN 355Y

INSPECTION









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R











LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKN 355Y

RE-INSPECTION

