



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2200535

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 26/01/2022
Reference CC4/FCI21013112/R1ra3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLN 3778D
Insured Veh. XD 4289C
Claim No. D21003498MFCV
Policy No.
Accident Date 20/12/2021
Inspection Date 28/12/2021

Description	Total
Survey Inspection	268.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	268.00
GST (7%)	18.76
Grand Total	286.76

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref: CC4/FCI21013112/R1ra3q2

Date: 26/01/2022

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 4289C	Veh. Inspected	SLN 3778D
Policy No.		Coverage (\$)	0.00
Claim No.	D21003498MFCV	Excess (\$)	0.00
Assign From	ERIC	Assign Date	24/12/2021

2. Vehicle Particulars & Condition

Make & Model	JAGUAR XJ 3.0S/C TSS SR	c.c	2995
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	SAJAC2281H8W05699	Colour	BLACK
Odometer	38585 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45Z R19	DUNLOP	6 mm
L/H Front Tyre	245/45Z R19	DUNLOP	6 mm
R/H Rear Tyre	245/45Z R19	DUNLOP	6 mm
L/H Rear Tyre	245/45Z R19	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/12/2021	Inspection Date	28/12/2021
Survey held at	HIN LUNG WORKSHOP BLK 1008 BUKIT MERAH LANE 3 #01-20 SINGAPORE 159722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 3778D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	SCRATCHED	2,787.00	2,787.00
1	FRONT BUMPER SIDE RETAINER LH	NOT NECESSARY	59.00	-
1	FRONT BUMPER SIDE RETAINER RH	NOT NECESSARY	59.00	-
10	BUMPER CLIPS @\$8.00	NECESSARY	80.00	80.00
1	FRONT BUMPER ENGINE COVER	DEFORMED	600.00	600.00
1	FRONT BUMPER IMPACT ABSORBER	NOT NECESSARY	325.00	-
1	FOG LAMP CHROME LH	CUT	404.00	404.00
	LESS 10% DISCOUNT		-	-387.10
			4,314.00	3,483.90
LABOUR				
	REPLACE NEW PARTS ,REMOVE /REFIT ALL ATTACHMENT PARTS TO FACILITATE REPAIR .		600.00	300.00
	SPRAY PAINT ON THE EFFECTED AREAS WITH 2K PAINT.		600.00	250.00
	CHECK WIRING AND PROPER FUNCTIONING.	NOT NECESSARY	60.00	-
			1,260.00	550.00
GRAND TOTAL			5,574.00	4,033.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CC4/FCI21013112/R1ra3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 3778D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 3778D

RE-INSPECTION

