



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: JANICE		Ref: CC4/ASM21013121/Dpa3q2 Date: 20/04/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLW 6871A	Veh. Inspected	GBK 2047X
Policy No.	P2203634	Coverage (\$)	0.00
Claim No.	S1M03PCI	Excess (\$)	0.00
Assign From		Assign Date	27/12/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTFAT35YX0K214727	Colour	SILVER
Odometer	72491 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/75 R15	BRIDGESTONE	5 mm
L/H Front Tyre	195/75 R15	BRIDGESTONE	5 mm
R/H Rear Tyre	155 R12C (D)	YOKOHAMA	5/5 mm
L/H Rear Tyre	155 R12C (D)	YOKOHAMA	5/5 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	23/12/2021	Inspection Date	27/12/2021
Survey held at	ALFRED AUTO SERVICES & SUPPLIES BLK 5035 ANG MO KIO 3 #01-355 ANG MO KIO INDUSTRIAL PARK 2 . SINGAPORE 569538		
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days