

TPAYA.
Denise.

SNA9463S 2021 July
Hyundai kona Hybrid. 1580cc
KMHK281EVMU070627.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rear Bumper Deformed	598.90 /
Rear Bumper Clips. ^{new}	30(SN) /
Rear Bumper Side Holder x02 ^{new}	40.8 x 2 = 81.60 /
Rear Bumper Reinforcement ^{could}	394.90 /
Rear Bumper Reinforcement Stay x02 ^{new}	121 x 2 = 242 X
Rear Bumper Reinforcement Bracket x02 ^{could}	18 x 2 = 36. /
Rear Bumper Lower Garnish. ^{could}	355.40 /
Reverse Sensor - ^{Damaged}	280(SN) - 220(SN)
Rear End Panel ^{Repair}	698.40 X
Rear End Panel Top Garnish. ^{Deformed}	289.40 /
Rear End Panel Top Garnish Clips. ^{new}	20(SN) /
Rear End Panel Sealant ^{new}	60(SN) X
Rear End Panel Antenna Sensor ^{new}	124.50 X
Rear Bumper Lower Lamp x02 ^{RH}	324 x 2 = 648
	324

SWA 94635

Tailhup Lower Bracket x 02 ^{MP} _m 34.1 x 2 = 68.20 x

Tailgate Reps 1540.40 x

Tailgate Lock } 224.10 x

Tailgate Weatherstripe } ^{MP} _m 204.20 x

Tailgate G/s) Sealant 60(SN) x

Hyundai Logo } 58.10 ✓

Kona Wording } ^{MP} _m 62.40 ✓

Hybrid Wording } 60.40 ✓

2261.10 S.W: 290.

1808.88

Panel Beating ~~1000~~ 600

Spray Painting ~~800~~ 600

Wiring 1390 ~~50~~ 30

To remove reverse sensor ~~100~~ 50

To spray tuff coat ~~150~~ 60

To remove upholstery. ~~150~~ 50

To transfer tailgate fittings. 150 x

To transfer tailgate g/s) 180 x

7580.90

total 3488.88

1/2: 2.8K.

04 Days

2.8K