



Your Ref : S1M03LJ1

Date: 03th Mar 2022

Our Ref : CS4/ASM21013127/Pqy3e2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Ong Kian Theng Derick

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLF 8855Z
ACCIDENT ON 03/11/2021**

Instruction was received to inspect the vehicle Reg. No. SLF 8855Z. The inspection was conducted on 27/12/2021 at the premises of M/s Ethoz Group Ltd, 30 Bukit Batok Crescent, Singapore 658075.

The following vehicle information was recorded:

Registration Number	: SLF 8855Z
Make/Model	: Jeep Wrangler Sport
Year of Registration	: 2009
Body Colour	: Green
Chassis Number	: 1J4FE24198L639718
Engine Capacity	: 3778 cc
Speedometer Reading	: Nil

The vehicle caught fire. The cause of fire probably due to short circuit. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 103,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 25,938.00)
Nett Liability	<u>S\$ 77,062.00</u> =====

Vehicle Inspected By:



SHERWIN BEH SWEE YANG
Technical Investigator



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.