



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 6963R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DISTORTED	1,395.90	1,395.90
1	REAR BUMPER DIFFUSER	DEFORMED	407.13	407.13
1	REAR BUMPER REINFORCEMENT	DENTED	488.57	488.57
1	REAR BUMPER SIDE RETAINER (RH)	NOT NECESSARY	56.02	-
1	SET REAR BUMPER CLIP	NECESSARY	50.00	50.00
1	REAR BUMPER REFLECTOR (RH)	CRACKED	53.50	53.50
	LESS 10% DISCOUNT		-245.11	-239.51
			2,206.01	2,155.59
<u>SPECIAL NETT ITEMS</u>				
2	REVERSE SENSOR (SN)	DAMAGED (1PC ONLY)	359.55	179.77
			359.55	179.77
<u>LABOUR</u>				
	TO REMOVE & REINSTALL REVERSE SENSORS.		120.00	50.00
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		120.00	30.00
	LABOUR TO REMOVE, CUT, CHANGE & PANEL BEATING.		750.00	200.00
	TO PUTTY AND RESPRAY AFFECTED AREAS.		650.00	200.00
			1,640.00	480.00
GRAND TOTAL			4,205.56	2,815.36
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CS/FCI21013128/Atf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.