

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21013129/KVF3E2**Date:** 17/01/2022**REFERENCE**

Insured/Claimant:	COMFORTDELGRO RENT-A-CAR PTE LTD	Policy No:	D20MFL0000326-01
Date of Loss:	11/12/2021	Nature of Claim:	OD Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ6698T	Engine No:	2AR2596406
Make & Model:	TOYOTA VELLFIRE, 2.5 Z G-EDITION CVT (A)	Chassis No:	AGH300361728
Reg. Date:	28/06/2021 (Man. Year: 2021)	Odometer:	24162 km
Colour:	Metallic Black		
Engine Capacity:	2493 cc		
Market Value/New Car Price:	S\$182,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Toyo 8 mm	Rear Left Side:	Toyo 8 mm
Front Right Side:	Toyo 8 mm	Rear Right Side:	Toyo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,734.55	10,869.30	4,865.25	30.92
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,010.00	1,370.00	640.00	31.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,755.55	12,250.30	5,505.25	31.01
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	17,755.55	11,500.30	6,255.25	35.23
+ GST 7.00/7.00% (S\$)	1,242.89	805.02	437.87	35.23
Nett Amount (S\$)	18,998.44	12,305.32	6,693.12	35.23

INSPECTION

Date of Assignment:	28/12/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Braddell)
Date Inspected:	27/12/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Jan 2022)

Parts: M1-MPV TOYOTA VELLFIRE 2.5 Z G-EDITION CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLZ6698T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	864.00 FL	*- FL
2	1		*BONNET LOCK	Repair	139.00 FL	*- FL
3	1		*BONNET HINGE RH	Distorted	65.00 FL	*65.00 FL
4	1		*BONNET HINGE LH	Repair	65.00 FL	*- FL
5	1		*HEADLAMP RH	Cracked	9,727.00 FL	*7,295.00 FL
6	1		*HEADLAMP LOWER BRACKET RH	Repair	378.00 FL	*- FL
7	1		*FRONT BUMPER	Bent	2,332.00 FL	*2,332.00 FL
8	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	105.00 FL	*105.00 FL
9	1		*FRONT BUMPER SIDE GARNISH	Cracked	1,281.00 FL	*1,281.00 FL
10	1		*FRONT BUMPER CHROME TOP	Cracked	282.00 FL	*282.00 FL
11	1		*FRONT BUMPER SIDE GARNISH CHROME	Dented	160.00 FL	*160.00 FL
12	1		*FRONT BUMPER SENSOR	Shorted	420.00 FL	*420.00 FL
13	1		*FRONT RH FENDER	Buckled	1,373.00 FL	*1,373.00 FL
14	1		*FRONT GRILLE WITH CHROME	Serviceable	2,609.00 FL	*- FL
Supplementary #1						
15	1		*FRT BUMPER SPONGE	Cracked	102.30 FL	*102.30 FL
16	1		*FRT BUMER LOWER GRILLE	Cracked	268.50 FL	*268.50 FL
17	1		*FRT BUMPER LOWER COVER	Dented	195.70 FL	*195.70 FL
18	1		*RH SIDE AIR GUIDE	Cracked	115.20 FL	*115.20 FL
19	1		*FRT SUPPORT PANEL VERTICAL PANEL RH	Bent	377.50 FL	*377.50 FL
20	1		*HEADLAMP GARNISH	Cracked	120.20 FL	*120.20 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	20,979.40	14,492.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,244.85	3,623.10
Total Parts (\$\$)	15,734.55	10,869.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK ,STRAIGHTEN AND RENEW ACCIDENT AREAS SUCH AS BONNET,FRT BUMPER,RH FRT FENDER,FRT SUPPORT PANEL ,RH HEADLAMP AND ETC.	New	960.00	600.00
2	TO PUTTY,RESPRAY ACCIDENT AREAS SUCH AS BONNET FRT BUMPER FRT EH FENDER,FRT SUPPORT PANEL AND ETC	New	1,000.00	750.00
3	TO CHECK LIGHTING AND WIRING	New	50.00	20.00
Gross Labour Cost (\$\$)			2,010.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >