

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	▼	🖨	📄	Find Next
---	---	---	--------	---	---	---	---	------	---	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO21013133/Utf3e2	
50 RAFFLES PLACE #03-03 SINGAPORE LAND		Date: 07/01/2022	
TOWER SINGAPORE 048623		Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	YP 1838M	Veh. Inspected	SJL 5703R
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2103806/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	27/12/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA CRV (A)	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JHLRE28308C201029	Colour	RED
Odometer	143320 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/65 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/65 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/65 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/65 R17	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.			
5. General Information			
Accident Date	22/12/2021	Inspection Date	28/12/2021
Survey held at	PAUL HOE BATTERIES & MOTOR SERVICES BLK 1 KAKI BUKIT AVE 6 #01-109 AUTOBAY SINGAPORE 417833		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	