




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT   |  |   |   |   |
|--|--|---|---|---|
| MS FIRST CAPITAL INSURANCE LTD<br>36 ROBINSON ROAD #16-01 CITY HOUSE<br>SINGAPORE 068877 |  |   | Ref: CS3/FCI21013137/Gqf3e2<br>Date: 07/01/2022<br>Code: FCI2 |   |
| 1. Policy Particulars :- (THIRD PARTY CLAIM)   |  |   |   |   |
|  | Insured Veh.   | SBS 6390K   | Veh. Inspected  | SJB 2217A   |
|  | Policy No.   |   | Coverage (\$)   | 0.00  |
|  | Claim No.  | D21003528MFBP   | Excess (\$)   | 0.00  |
|  | Assign From  | AINI BINTE  | Assign Date   | 27/12/2021  |
| 2. Vehicle Particulars & Condition   |  |   |   |   |
|  | Make & Model   | MAZDA 3   | c.c   | 1496  |
|  | Engine No.   | HIDDEN  | Year of Reg.  | 2017  |
|  | Chassis No.  | JM6BN22A8H0172625   | Colour  | BLACK   |
|  | Odometer   | 98099 KM  | Steering  | IN ORDER  |
|  | Brakes   | IN ORDER  | Modification  | STANDARD ALLOY RIM  |
|  | General  | GOOD  |   |   |
| 3. Conditions of Tyres   |  |   |   |   |
|  |  | Size  | Make  | Balance   |
|  | R/H Front Tyre   | 205/60 R16  | YOKOHAMA  | 6 mm  |
|  | L/H Front Tyre   | 205/60 R16  | YOKOHAMA  | 6 mm  |
|  | R/H Rear Tyre  | 205/60 R16  | YOKOHAMA  | 6 mm  |
|  | L/H Rear Tyre  | 205/60 R16  | YOKOHAMA  | 6 mm  |
| 4. Description of Damages  |  |   |   |   |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.  |   |   |  |
| 5. General Information   |  |   |   |   |
|  | Accident Date  | 23/12/2021  | Inspect Date / Time   | 06/01/2022 ( 12:00 PM )   |
|  | Survey held at   | KING'S AUTO REPAIR & SERVICE PTE LTD<br>176 SIN MING DRIVE, #02-10, SIN MING AUTOCARE, SINGAPORE 575721 |   |   |
| 5a. Remarks  |  |   |   |   |
|  | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.<br>D)MARKET VALUE:\$58,000.00 |   |   |   |

Report Ref No. CS3/FCI21013137/Gqf3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or  
relying on this Report, in whole or in part, does so at his or her own risk.