

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013138/UTY3N2**Date:** 28/01/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00260332100

Claimant Vehicle No : SLV2793Z **Insured Vehicle No :** SGE7272B

Date of Loss: 21/12/2021 Nature of Claim: TP Claim No: SNM21D207478/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV2793Z**

Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: 2ZR8202882

Reg. Date: 27/12/2017 (Man. Year: 2017) Chassis No: ZYX102078162

Colour: Black Odometer: 17405 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60R17 Rear Tyre Size: 215/60R17

Front Left Side: Tourador 8 mm Rear Left Side: Tourador 8 mm

Front Right Side: Tourador 8 mm Rear Right Side: Tourador 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,203.50	1,895.00	4,308.50	69.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	1,530.00	710.00	31.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,443.50	3,425.00	5,018.50	59.44
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	8,443.50	2,700.00	5,743.50	68.02
+ GST 7.00/7.00% (S\$)	591.05	189.00	402.05	68.02
Nett Amount (S\$)	9,034.55	2,889.00	6,145.55	68.02

INSPECTION

Date of Assignment: 27/12/2021

Date Inspected: 28/12/2021 Inspected At: Progressive Automotive Pte Ltd - Ubi (HQ)
BLK 3022A UBI ROAD 1 #01-45/46,
Singapore 048716

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 Jan 2022)**Parts:** M1-SUV TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLV2793Z)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	353.00 FL	*353.00 FL
2	1		*REAR BUMPER LOWER	Distorted	375.00 FL	*375.00 FL
3	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
4	2		*REAR BUMPER SIDE HOLDER-RH/LH	Not Necessary	204.00 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	322.00 FL	*322.00 FL
6	1		*REAR BUMPER CENTRE LOWER COVER	Torn	104.00 FL	*104.00 FL
7	1		*REAR EXHAUST PIPE	Repair	1,719.00 FL	*- FL
8	1		*REAR EXHAUST PIPE TOP PLATE	Bent	165.00 FL	*165.00 FL
9	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	40.00 FL	*- FL
10	1		*REAR PANEL	Dented/Bent	716.00 FL	*716.00 FL
11	1		*REAR PANEL TOP GARNISH	Not Necessary	254.00 FL	*- FL
12	1		*REAR BOOT	Repair	1,250.00 FL	*- FL
13	1		*REAR BOOT LOWER GARNISH	Not Necessary	925.00 FL	*- FL
14	1		*SET REAR BOOT GLASS MOULDING	Not Necessary	180.00 FL	*- FL
15	2		*TAILLAMP ASSY-RH/LH	Not Necessary	886.00 FL	*- FL
16	2		*TAILLAMP LOWER RETAINER-RH/LH	Not Necessary	120.00 FL	*- FL
17	1		*REAR BUMPER SIDE GARNISH N/S	Torn	175.00 FL	*175.00 FL
18	2		*SEALANT	Not Necessary	40.00 FS	*- FS
19	1		*SPONGE TAPE	Not Necessary	20.00 FS	*- FS
20	1		*REAR NUMBER PLATE WITH CASING	Not Necessary	45.00 FS	*- FS
21	1		*SET REAR BUMPER SENSOR	Shorted	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,163.00	2,460.00
- List Item Discount on L Items 25.00/25.00% (\$)	1,959.50	565.00
Total Parts (\$)	6,203.50	1,895.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS,CUT/WELD REAR BOTH FENDER RH,REMOVE,REPLACE ACCIDENT PARTS	New	900.00	600.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	800.00	750.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO TRANSFER REAR BUMPER SENSOR	New	100.00	50.00
5	TO TUFF-KOTE	New	60.00	30.00
6	TO REMOVE,REFIT REAR GARNISH	New	80.00	80.00
7	TO REMOVE,REPLACE REAR EXHAUST PIPE	New	100.00	0.00
8	TO REMOVE,REFIX REAR BOOT GLASS	New	150.00	0.00
			Gross Labour Cost (\$\$)	2,240.00
				1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >