

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013144/AVY3N2**Date:** 06/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00083152103

**Claimant Vehicle
No :** PC3301G**Insured Vehicle
No :** GX6A

Date of Loss: 25/12/2021

Nature of Claim: TP

Claim
No: SNM21D207574/C02/TAYHP**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **PC3301G**

Make & Model: NISSAN NV350, 2.5 (A)

Engine No: YD25353623A

Reg. Date: 28/11/2014 (Man. Year: 2014)

Chassis No: JN1UC4E26Z0001938

Colour: Silver

Odometer: 323833 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15C

Rear Tyre Size:

195R15C

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,781.79	6,582.13	14,199.66	68.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,420.00	2,650.00	3,770.00	58.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,201.79	9,232.13	17,969.66	66.06
Approved Total (Overridden) (\$\$)		7,300.00		
Nett Amount (\$\$)	27,201.79	7,300.00	19,901.79	73.16

INSPECTION

Date of Assignment: 19/04/2022

Date Inspected: 28/12/2021 Inspected At:

HD Perfect Autowork Pte Ltd (HQ)

8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 May 2022)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC3301G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	632.70 FL	*632.70 FL
2	1		*REAR BUMPER STEP PANEL	Bent	269.60 FL	*269.60 FL
3	2		*REAR BUMPER SIDE SPONGE	Cracked	156.00 FL	*156.00 FL
4	1		*TAIL GATE	Dented	2,247.10 FL	*2,247.10 FL
5	1		*TAIL GATE CATCH	Not Necessary	31.80 FL	*- FL
6	2		*TAIL GATE SIDE STOPPER	Not Necessary	38.00 FL	*- FL
7	1		*TAIL GATE STOPPER	Not Necessary	28.00 FL	*- FL
8	2		*TAIL GATE DAMPER	Not Necessary	350.80 FL	*- FL
9	2		*TAIL GATE HINGE	Not Necessary	125.80 FL	*- FL
10	1		*TAIL GATE VIEW MIRROR	Not Necessary	298.10 FL	*- FL
11	1		*TAIL GATE OUTER MOULDING	Cracked	463.90 FL	*463.90 FL
12	1		*TAIL GATE OUTER HANDLE	Not Necessary	398.10 FL	*- FL
13	1		*TAIL GATE OUTER KEY LOCK	Not Necessary	278.40 FL	*- FL
14	1		*TAIL GATE INNER LOCK	Damaged	394.10 FL	*394.10 FL
15	1		*TAIL GATE INNER LOCK MOTOR	Not Necessary	267.30 FL	*- FL
16	1		*TAIL GATE CENTER LOCK MOTOR	Not Necessary	395.30 FL	*- FL
17	1		*TAIL GATE LOWER LOCK COVER	Cut	85.00 FL	*85.00 FL
18	2		*TAIL GATE NUMBER PLATE LAMP	Not Necessary	96.60 FL	*- FL
19	1		*TAIL GATE INNER TRIM	Torn	298.40 FL	*165.00 FL
20	1		*TAIL GATE EMBLEM NV350	Necessary	89.70 FL	*89.70 FL
21	1		*TAIL GATE EMBLEM URVAN	Necessary	78.90 FL	*78.90 FL
22	1		*TAIL GATE WEATHERSTRIP	Cut	395.00 FL	*395.00 FL
23	1		*TAIL GATE WEATHERSTRIP PROTECTOR	Bent	485.20 FL	*252.00 FL
24	1		*TAIL GATE WINDSCREEN GLASS	Not Necessary	1,396.90 FL	*- FL
25	2		*TAIL LAMP	Cracked	597.40 FL	*597.40 FL
26	2		*TAIL LAMP PANEL	Repair	1,189.80 FL	*- FL
27	2		*TAILLAMP INNER PANEL	Repair	1,174.20 FL	*- FL
28	1		*REAR END PANEL (OUTER)	Dented	461.60 FL	*461.60 FL
29	1		*REAR END PANEL (INNER)	Repair	986.70 FL	*- FL
30	1		*REAR END PANEL (EXTEND)	N/s Dented	995.40 FL	*497.70 FL
31	1		*REAR FLOOR PANEL	Repair	1,883.20 FL	*- FL
32	1		*REAR FLOOR MAT	Not Necessary	981.60 FL	*- FL
33	1		*REAR EXHAUST PIPE	Not Necessary	691.40 FL	*- FL
34	3		*REAR EXHAUST MOUNTING	Not Necessary	86.10 FL	*- FL
35	1		*REAR EXHAUST GASKET (SET)	Not Necessary	65.00 FL	*- FL
36	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
37	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
38	1		*SET TAIL GATE INNER TRIM CLIP	Necessary	50.00 FS	*20.00 FS
39	1		*SET TAIL GATE OUTER MOULDING CLIP	Necessary	30.00 FS	*20.00 FS
40	1		*TAIL GATE STICKER 70KM/H	Necessary	30.00 FS	*15.00 FS
41	1		*TAILGATE CENTER MOULDING EMERGENCY DOOR STICKER	Necessary	50.00 FS	*20.00 FS
42	1		*TAILGATE PULL TO OPEN STICKER	Necessary	50.00 FS	*20.00 FS
43	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
44	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
45	1		*TAIL GATE WINDSCREEN SOLAR FILM	Not Necessary	550.00 FS	*- FS
46	1		*SET TAIL LAMP CLIP	Necessary	30.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*TAILLAMP PANEL SEALANT	Not Necessary	60.00 FS	*- FS
48	1		*REAR END PANEL (OUTER) SEALANT	Necessary	150.00 FS	*60.00 FS
49	1		*REAR END PANEL (INNER) SEALANT	Not Necessary	150.00 FS	*- FS
50	1		*REAR END PANEL (EXTEND) SEALANT LH	Not Necessary	80.00 FS	*- FS
51	1		*REAR FLOOR PANEL SEALANT	Not Necessary	350.00 FS	*- FS
52	1		*REAR FLOOR TOP WOODEN BOARD (SPECIAL)	Not Necessary	1,200.00 FS	*- FS
53	1		*REAR SPARE TYRE	Not Necessary	360.00 FS	*- FS
54	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
55	1		*REVERSE CAMERA	Not Necessary	550.00 FS	*- FS
Sub Total (\$\$)						22,623.107,260.70
- List Item Discount on L Items 10.00/10.00% (\$\$)						1,841.31678.57
Total Parts (\$\$)						20,781.796,582.13

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVING AND REPLACING PARTS	New	2,000.00	1,100.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	1,100.00
3	WIRING BULB CHECKING	New	250.00	30.00
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	650.00	60.00
5	TUFF COAT	New	250.00	60.00
6	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
7	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
8	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
9	REAR CHASSIS ALIGNMENT	New	250.00	0.00
10	REMOVE AND REFIX REAR REVERSE SENSOR	New	80.00	50.00
11	REMOVE AND REFIX REAR REVERSE CAMERA	New	80.00	50.00
12	REMOVE AND REFIX FLOOR BOARD	New	480.00	0.00
13	REMOVE AND REFIX REAR EXHAUST PIPE	New	120.00	0.00
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$)			6,420.00	2,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >