



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2200513

INV Date 25/01/2022

Reference CC4/FCI21013146/Kga3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLR 8313H
Insured Veh. GBD 6373P
Claim No. D21003536MFCV
Policy No.
Accident Date 25/12/2021
Inspection Date 04/01/2022

Description	Total
Survey Inspection	261.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	261.00
GST (7%)	18.27
Grand Total	279.27

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CC4/FCI21013146/Kga3q2 Date: 25/01/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 6373P	Veh. Inspected	SLR 8313H
Policy No.		Coverage (\$)	0.00
Claim No.	D21003536MFCV	Excess (\$)	0.00
Assign From	CHRIS	Assign Date	27/12/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU31247339	Colour	METALLIC GREY
Odometer	57548 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	TRIANGLE	9 mm
L/H Front Tyre	215/55 R17	TRIANGLE	9 mm
R/H Rear Tyre	215/55 R17	TRIANGLE	9 mm
L/H Rear Tyre	215/55 R17	TRIANGLE	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/12/2021	Inspection Date	04/01/2022
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 8313H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT LH HEADLAMP	MTG CRACKED	1,759.40	1,759.40
1	FRONT LH HEADLAMP LOWER BRACKET	TO REPAIR SEE LABOUR	45.00	-
1	FRONT BUMPER	BUCKLED	927.50	726.60
20	FRONT BUMPER CLIP @\$5.00	NECESSARY	100.00	100.00
1	FRONT BUMPER GRILLS	SERVICEABLE	195.20	-
1	FRONT BUMPER LOWER LID	SERVICEABLE	485.50	-
1	FRONT BUMPER LH SIDE RETAINER	DISTORTED	38.10	38.10
1	FRONT BUMPER LH FOG LAMP	SERVICEABLE	385.50	-
1	FRONT BUMPER LH FOG LAMP BASE	SERVICEABLE	85.50	-
1	FRONT BUMPER LH FOG LAMP GARNISH	SERVICEABLE	125.50	-
1	FRONT CENTRE GRILLE BASE	CRACKED	480.50	351.80
1	FRONT CENTRE GRILLE OUTER GARNISH	SERVICEABLE	385.20	-
1	FRONT WIPER TANK	SERVICEABLE	280.50	-
1	FRONT LH FENDER PROTECTOR	SERVICEABLE	195.00	-
	LESS 20% DISCOUNT		-1,097.68	-595.18
			4,390.72	2,380.72
LABOUR				
	WIRING.		80.00	20.00
	SPRAY PAINTING.		800.00	220.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF FRONT LH HEADLAMP LOWER BRACKET.		800.00	200.00
			1,680.00	440.00
GRAND TOTAL			6,070.72	2,820.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CC4/FCI21013146/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 8313H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 8313H

RE-INSPECTION

