

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21013149/UVY3E2

Date: 21/01/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00077882101
Claimant Vehicle No : FBL1600A **Insured Vehicle No :** SJQ7200K
Date of Loss: 21/12/2021 Nature of Claim: TP Claim No: SNM21D207532/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBL1600A**
Make & Model: HONDA CB400SF, 399cc Engine No: NC42E1205381
Reg. Date: 23/06/2016 (Man. Year: 2016) Chassis No: NC421800215
Colour: Red/Grey Odometer: 78645 km
Engine Capacity: 399 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60Z R17 Rear Tyre Size: 160/60Z R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	830.00	732.80	97.20	11.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	252.00	220.00	32.00	12.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,082.00	952.80	129.20	11.94
Approved Total (Overridden) (S\$)		760.00		
(S\$)	1,082.00	760.00	322.00	29.76
+ GST 7.00/7.00% (S\$)	75.74	53.20	22.54	29.76
Nett Amount (S\$)	1,157.74	813.20	344.54	29.76

INSPECTION

Date of Assignment: 17/01/2022
Date Inspected: 27/12/2021 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)
Estimated Period of Repair: 3.0 days No. 6 Defu Lane 4
Singapore 539410

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Jan 2022)	
Parts:	N/A	HONDA CB400SF 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL1600A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOLT FOOTREST	Cut	10.00 F	*10.00 FL
2	1		*BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT	Cut	230.00 F	*230.00 FL
3	1		*CRASH BAR (ENGINE)	Cut	196.00 F	*196.00 FL
4	1		*LEVER BRAKE	Scratched	70.00 F	*70.00 FL
5	1		*MIRROR RH	Cut	126.00 F	*126.00 FL
6	1		*MUDGUARD REAR ASSY	Broken	160.00 F	*160.00 FL
7	1		*MUFFLER (REAR) YOSHIMURA (NPA)	Serviceable	0.00 F	*- FL
8	1		*PLATE NUMBER REAR ACRYLIC (YELLOW)	Broken	38.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	830.00	812.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	79.20
Total Parts (\$\$)	830.00	732.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	252.00	220.00
Gross Labour Cost (\$)			252.00	220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >