



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 8442Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	FRONT BUMPER (CONSISTENT)	CUT / BUCKLED	1,245.00	927.50
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	DISTORTED	220.00	160.00
1	HEADLAMP LH (CONSISTENT)	MTG CRACKED	980.00	980.00
1	FRONT FENDER LH (CONSISTENT)	BUCKLED	480.00	480.00
1	FRONT FENDER UNDERSHIELD LH (CONSISTENT)	CRACKED	323.45	168.50
1	FRONT WHEEL HUB LH (CONSISTENT)	SERVICEABLE	380.00	-
1	FRONT WHEEL BEARING LH (CONSISTENT)	NECESSARY	330.00	132.40
1	FRONT SUSPENSION LH (CONSISTENT)	BENT	580.00	368.60
1	FRONT LOWER ARM LH (CONSISTENT)	DISTORTED	485.00	419.70
1	FRONT KNUCKLE LH (CONSISTENT)	BENT	440.00	440.00
1	FRONT STAILIZER BAR LH (CONSISTENT)	SERVICEABLE	280.00	-
1	FRONT TIE ROD END LH (CONSISTENT)	SERVICEABLE	233.50	-
	LESS 25% DISCOUNT		-1,494.24	-1,019.18
			4,482.71	3,057.52
<u>SPECIAL NETT ITEMS</u>				
1	FRONT RIM LH (SN) (CONSISTENT)	DENTED	800.00	280.00
10	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	45.00	45.00
10	FRONT FENDER UNDERSHIELD CLIPS (SN) (CONSISTENT)	NECESSARY	45.00	45.00
			890.00	370.00
<u>LABOUR</u>				
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF BONNET.		1,000.00	400.00
	LABOUR TO REPLACE FRONT RIGHT UNDERCARRIAGE.		280.00	200.00
	TO DO COMPUTER WHEEL ALIGNMENT.		80.00	60.00
	CHECK WIRING SYSTEM, FOCUS HEADLAMP.		120.00	20.00
	ANTI RUST.		80.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DO SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		1,000.00	400.00
			2,560.00	1,110.00
GRAND TOTAL			7,932.71	4,537.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,600.00

Report Ref No. CS/ASM21013161/Kty3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.