



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 3383L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR SIDE MIRROR RH	DISTORTED	534.60	534.60
1	FRONT DOOR SIDE MIRROR COVER RH	MISSING	243.10	243.10
1	FRONT DOOR SIDE MIRROR GLASS RH	MISSING	486.70	486.70
1	FRONT DOOR OUTER MOULDING RH	CUT	210.60	210.60
1	FRONT FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT BONNET (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-295.00	-295.00
			1,180.00	1,180.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH AND FRONT BONNET.		650.00	200.00
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		850.00	700.00
			1,500.00	900.00
	GRAND TOTAL		2,680.00	2,080.00
	RECOMMENDED COST OF REPAIRS			2,080.00

Report Ref No. CS/SMR21013164/Gtf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.