

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21013166/KEA3Q2**Date:** 30/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210035323
<b>Claimant Vehicle No :</b>	SLB5861X	<b>Insured Vehicle No :</b>	SBJ4000Y
Date of Loss:	22/12/2021	Nature of Claim:	TP
		Claim No:	8502520917SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLB5861X</b>	Engine No:	L15B4029271
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11109268
Reg. Date:	14/04/2016 (Man. Year: 2015)	Odometer:	102456 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Nexen 8 mm	Rear Left Side:	Nexen 8 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Nexen 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,890.72	1,914.94	975.78	33.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	935.00	1,045.00	52.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,870.72</b>	<b>2,849.94</b>	<b>2,020.78</b>	<b>41.49</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,250.00</b>		
<b>(S\$)</b>	4,870.72	2,250.00	2,620.72	53.81
<b>+ GST 7.00/7.00% (S\$)</b>	340.95	157.50	183.45	53.81
<b>Nett Amount (S\$)</b>	<b>5,211.67</b>	<b>2,407.50</b>	<b>2,804.17</b>	<b>53.81</b>
<b>+ Car Rental (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,809.50</b>		

INSPECTION

Date of Assignment:	27/12/2021	Ah Lim Motor Company (AMK)
Date Inspected:	28/12/2021 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING TOP	Necessary	42.10 FL	*42.10 FL
2	2		*REAR WINDSCREEN MOULDING LH & RH	Necessary	62.40 FL	*62.40 FL
3	1		*REAR WINDSCREEN MOULDING TRIM	Necessary	28.40 FL	*28.40 FL
4	1		*TAILGATE	Bent	901.70 FL	*901.70 FL
5	1		*TAILGATE EMBLEM	Not Necessary	30.10 FL	*- FL
6	1		*TAILGATE VEZEL LOGO	Necessary	43.10 FL	*43.10 FL
7	1		*TAILGATE LAMP RH	Serviceable	38.50 FL	*- FL
8	1		*TAILGATE STOPPER RH	Serviceable	15.10 FL	*- FL
9	1		*TAILGATE LOCK	Repair	130.10 FL	*- FL
10	1		*TAILGATE RUBBER	Serviceable	101.30 FL	*- FL
11	1		*TAILGATE INNER TRIM BOARD BTM	Serviceable	153.40 FL	*- FL
12	1		*TAILLAMP RH	Serviceable	503.10 FL	*- FL
13	1		*REAR BUMPER	Bent	553.10 FL	*553.10 FL
14	1		*REAR BUMPER REFLECTOR RH	Serviceable	50.10 FL	*- FL
15	1		*REAR BUMPER CORNER RH	Dented / Buckled	195.10 FL	*195.10 FL
16	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	17.50 FL	*- FL
17	12		*REAR BUMPER CLIPS	Necessary	70.68 FL	*70.68 FL
18	1		*REAR FENDER WHEEL ARCH RH	Buckled	172.10 FL	*172.10 FL
19	1		*REAR FENDER COWLING RH	Serviceable	133.40 FL	*- FL
20	8		*REAR FENDER COWLING CLIPS	Not Necessary	47.12 FL	*- FL
21	1		*SET REVERSE SENSOR	Scratched	200.00 FS	*200.00 FS
22	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
23	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
					<b>Sub Total (S\$)</b>	<b>3,548.40      2,328.68</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>657.68      413.74</b>
					<b>Total Parts (S\$)</b>	<b>2,890.72      1,914.94</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	15.00
2	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR WINDSCREEN	New	120.00	120.00
3	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	50.00
4	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
5	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD TO KNOCK & REPAIR REAR FENDER RH ,REAR END PANEL INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	800.00	400.00
6	TO SPRAY TAILTATE,REAR BUMPER ,REAR FENDER LH ,REAR END PANEL	New	900.00	320.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,980.00</b>	<b>935.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >