

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21013180/KGA3Q2**Date:** 19/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070164626-01
<b>Claimant Vehicle No :</b>	SMP5678Z	<b>Insured Vehicle No :</b>	SMW5003J
Date of Loss:	24/12/2021	Nature of Claim:	TP
		Claim No:	9864382743SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMP5678Z</b>	Engine No:	G4LEMU144533
Make & Model:	HYUNDAI AE IONIQ, 1.6 (A)	Chassis No:	KMHC851CVMU265738
Reg. Date:	03/11/2021 (Man. Year: 2021)	Odometer:	8873 km
Colour:	Black		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,463.32	1,303.88	159.44	10.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	1,110.00	270.00	19.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>2,843.32</b>	<b>2,413.88</b>	<b>429.44</b>	<b>15.10</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	199.03	168.97	30.06	15.10
<b>Nett Amount (\$\$)</b>	<b>3,042.35</b>	<b>2,582.85</b>	<b>459.50</b>	<b>15.10</b>
<b>+ Car Rental (3.0 x S\$86.00/day) (\$\$)</b>		258.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>2,842.85</b>		

INSPECTION

Date of Assignment:	27/12/2021	
Date Inspected:	27/12/2021 Inspected At:	City Auto Pte Ltd ( Sin Ming) (HQ) Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est Singapore 575643
Estimated Period of Repair:	3.0 days	

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*NUMBER PLATE LAMP	Serviceable	136.80 FL	*- FL
2	1		*REAR BUMPER	Buckled	489.40 FL	*489.40 FL
3	1		*REAR BUMPER TRIM COVER	Buckled	216.50 FL	*216.50 FL
4	1		*REAR BUMPER LAMP CENTER	Cracked	201.50 FL	*201.50 FL
5	1		*REAR BUMPER REINFORCEMENT	Cracked	294.80 FL	*294.80 FL
6	12		*REAR BUMPER CLIPS	Necessary	58.80 FL	*58.80 FL
7	1		*EMBLEM -IONIQ	Necessary	34.30 FL	*34.30 FL
8	1		*EMBLEM -HYBRID	Necessary	28.30 FL	*28.30 FL
9	1		*NUMBER PLATE	Bent	20.00 FS	*20.00 FS
10	1		*NUMBER PLATE CASING	Bent	25.00 FS	*25.00 FS
11	1		*REVERSE SENSOR	Dented	250.00 FS	*200.00 FS
					Sub Total (\$\$)	1,755.40 1,568.60
					- List Item Discount on L Items 20.00/20.00% (\$\$)	292.08 264.72
					Total Parts (\$\$)	1,463.32 1,303.88

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING AND LIGHTING	New	40.00	20.00
2	TO INSTALL REVERSE SENSOR	New	40.00	40.00
3	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	600.00	450.00
4	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	700.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,380.00</b>	<b>1,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >