

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21013181/DPA3Q2  
**Date:** 19/04/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210146184
<b>Claimant Vehicle No :</b>	SHB4316H	<b>Insured Vehicle No :</b>	SGX946L
Date of Loss:	23/12/2021	Nature of Claim:	TP
		Claim No:	4224164491SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHB4316H</b>	Engine No:	G4LEKU400219
Make & Model:	HYUNDAI AE IONIQ, 1.6 (A)	Chassis No:	KMHC851CVLU187228
Reg. Date:	25/10/2019 (Man. Year: 2019)	Odometer:	297612 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	26,335.10	14,912.20	11,422.90	43.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,850.00	2,890.00	3,960.00	57.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>33,185.10</b>	<b>17,802.20</b>	<b>15,382.90</b>	<b>46.35</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,322.96</b>	<b>1,246.15</b>	<b>1,076.81</b>	<b>46.36</b>
<b>Nett Amount (S\$)</b>	<b>35,508.06</b>	<b>19,048.35</b>	<b>16,459.71</b>	<b>46.35</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment:	27/12/2021	
Date Inspected:	27/12/2021	Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644
Estimated Period of Repair:	8.0 days	

**Adjuster:** BRYAN TANI**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	2,480.40 FL	*2,480.40 FL
2	1		*BOOT LID RUBBER	Deformed	187.40 FL	*187.40 FL
3	1		*BOOT LID HINGE (RH)	Not Necessary	71.30 FL	*- FL
4	1		*BOOT LID ABSORBER (RH)	Not Necessary	86.70 FL	*- FL
5	1		*BOOT LID LOCK UPPER	Damaged	224.00 FL	*224.00 FL
6	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
7	1		*EMBLEM -HYBRID	Necessary	24.30 FL	*24.30 FL
8	1		*EMBLEM -LONIQ	Necessary	31.30 FL	*31.30 FL
9	1		*BOOT LID LAMP (RH)	Cracked / Cut	794.40 FL	*794.40 FL
10	1		*BOOT LID TRIMBOARD	Serviceable	259.70 FL	*- FL
11	10		*BOOT LID TRIMBOARD CLIPS	Serviceable	11.00 FL	*- FL
12	1		*BOOT LID TRIMBOARD ,CENTRE	Not Necessary	159.60 FL	*- FL
13	1		*BOOT LID TRIMBOARD SIDE (RH)	Not Necessary	92.50 FL	*- FL
14	1		*BOOT LID TRIMBOARD REAR	Not Necessary	124.80 FL	*- FL
15	1		*BOOT LID GLASS UPPER MOULDING	Not Necessary	186.30 FL	*- FL
16	1		*BOOT LID GLASS LOWER MOULDING	Not Necessary	145.20 FL	*- FL
17	1		*REAR BUMPER	Torn	459.40 FL	*459.40 FL
18	1		*REAR BUMPER REINFORCEMENT	Cracked	394.80 FL	*394.80 FL
19	1		*REAR BUMPER REINFORCEMENT BRACKET (RH)	Bent	188.10 FL	*188.10 FL
20	1		*REAR BUMPER CENTRE MOULDING ASSY	Broken	451.25 FL	*451.25 FL
21	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Mtg Cracked	47.50 FL	*47.50 FL
22	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
23	1		*REAR BUMPER SIDE RETAINER (RH)	Cracked / Broken	85.80 FL	*85.80 FL
24	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
25	1		*REAR BUMPER UNDER CENTRE	Mtg Cracked	123.85 FL	*123.85 FL
26	1		*REAR BUMPER SIDE UNDER (RH)	Dislodged	123.10 FL	*123.10 FL
27	1		*REAR BUMPER REAR HOOK	Not Necessary	94.60 FL	*- FL
28	1		*REAR BUMPER REFLECTOR LAMP (RH)	Dislodged	82.90 FL	*82.90 FL
29	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	*- FL
30	1		*REAR BUMPER REVERSE LIGHT (PARKING BRAKE LIGHT)	Socket Broken	328.60 FL	*328.60 FL
31	1		*LICENCE LAMP	Not Necessary	193.53 FL	*- FL
32	1		*LICENCE LAMP WIRE	Not Necessary	135.80 FL	*- FL
33	1		*TAIL LAMP (RH)	Cut / Cracked	870.40 FL	*870.40 FL
34	1		*TAIL LAMP QUARTER PANEL (RH)	Dented	208.90 FL	*208.90 FL
35	1		*REAR PANEL	Dented	532.00 FL	*532.00 FL
36	1		*REAR PANEL GARNISH	Serviceable	346.80 FL	*- FL
37	1		*PANEL ASSY -REAR FLOOR SIDE (RH)	Dented	39.40 FL	*39.40 FL
38	1		*REAR FLOOR CHASSIS MEMBER (RH)	Repair	1,863.40 FL	*- FL
39	1		*REAR TRAY TOOLS BOX RH	Bent / Deformed	675.30 FL	*675.30 FL
40	1		*REAR TRAY LUGGS CENTER	Not Necessary	354.20 FL	*- FL
41	1		*EXHAUST SILENCER	Bent / Dented	943.50 FL	*943.50 FL
42	1		*EXHAUST PIPE HANGER	Not Necessary	29.20 FL	*- FL
43	1		*REAR FENDER (RH)	Dented	1,768.30 FL	*1,768.30 FL
44	1		*REAR FENDER INNER PANEL (RH)	Repair	1,406.20 FL	*- FL
45	1		*REAR FENDER SHIELD REAR PIECE (RH)	Not Necessary	173.60 FL	*- FL
46	1		*REAR FENDER SHIELD FRT PIECE (RH)	Not Necessary	165.50 FL	*- FL
47	1		*REAR FENDER CORNER INNER UPPER GARNISH (RH)	Not Necessary	486.70 FL	*- FL
48	1		*REAR FENDER AIR-DUCT (RH)	Deformed	87.30 FL	*87.30 FL
49	1		*REAR FENDER TRIM BOARD (RH)	Deformed	788.75 FL	*788.75 FL
50	1		*REAR FENDER TRIM BOARD TOP GARNISH (RH)	Not Necessary	167.90 FL	*- FL
51	1		*ASSY BSD BLIND SPOT RADAR (RH)	Broken	1,625.00 FL	*1,625.00 FL
52	1		*WIRING HARNESS BWS EXT	Repair	988.90 FL	*- FL
53	1		*REAR DOOR (RH)	Repair	1,789.90 FL	*- FL
54	1		*REAR DOOR LOCK ASSY	Not Necessary	306.40 FL	*- FL
55	1		*REAR DOOR TRIM BOARD (RH)	Not Necessary	613.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR TYRE RIM (RH)	Not Necessary	1,124.20 FL	*- FL
57	1		*REAR WHEEL HUP-CAP (RH)	Not Necessary	346.40 FL	*- FL
58	1		*REAR WHEELBEARING & HUB ASSY	Damaged	554.00 FL	*554.00 FL
59	1		*REAR TRAILING ARM (RH)	Bent	265.40 FL	*265.40 FL
60	1		*REAR ASSIST (RH)	Distorted	227.90 FL	*227.90 FL
61	1		*REAR SHOCK ABSORBER (RH)	Distorted	230.50 FL	*230.50 FL
62	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	133.10 FL	*- FL
63	1		*REAR ABSORBER STOPPER (RH)	Not Necessary	137.60 FL	*- FL
64	1		*REAR ABSORBER COVER (RH)	Not Necessary	175.60 FL	*- FL
65	1		*REAR CROSSMEMBER	Bent	1,468.70 FL	*1,468.70 FL
66	1		*STABILIZER BAR	Distorted	387.30 FL	*387.30 FL
67	1		*STABILIZER LINK (RH)	Distorted	147.30 FL	*147.30 FL
68	1		*REAR UPPER ARM (RH)	Distorted	239.50 FL	*239.50 FL
69	1		*REAR LOWER ARM (RH)	Distorted	393.10 FL	*393.10 FL
70	1		*REAR KNUCKLE ARM (RH)	Distorted	538.10 FL	*538.10 FL
71	1		*REAR WIRING ASSY	Not Necessary	1,521.50 FL	*- FL
72	1		*BOOT LID COMFORT LOGO & TEL NO.STICKER	Necessary	35.00 FS	*35.00 FS
73	1		*BOOT LID COMFORT CABLINK TEL NO.STICKER	Not Necessary	30.00 FS	*- FS
74	1		*REAR NO PLATE +TRIM COVER	Dislodged	45.00 FS	*45.00 FS
75	2		*REAR WINDSCREEN SEALANT	Necessary	92.00 FS	*40.00 FS
76	1		*REAR BUMPER RUBBER MAT	Deformed	50.00 FS	*50.00 FS
77	1		*REAR BUMPER REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
78	1		*REAR DOOR TEL NO.STICKER (RH)	Not Necessary	10.00 FS	*- FS
79	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Not Necessary	80.00 FS	*- FS
80	1		*REAR TYRE (RH) (50%)	Damaged	216.00 FS	*108.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>32,734.38</b>	<b>18,525.75</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	6,399.28	3,613.55
<b>Total Parts (S\$)</b>	<b>26,335.10</b>	<b>14,912.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	2,000.00	1,200.00
2	SPRAY PAINTING	New	1,600.00	1,000.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	240.00	80.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
10	RE-SET REAR ABS SYSTEM	New	400.00	0.00
11	REMOVE/REFIX FUEL TANK	New	80.00	0.00
12	REMOVE/REFIX EXHAUST PIPE	New	80.00	60.00
13	TRANSFER OF DOOR MECHANISM REAR	New	80.00	0.00
14	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
15	FOUR WHEEL ALIGNMENT	New	120.00	60.00
16	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	550.00	150.00
17	DIAGNOSTIC & RESETTING ADAS OPTICAL SENSOR }	New	550.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>6,850.00</b>
				<b>2,890.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >