



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 3611K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	DEFORMED	541.50	541.50
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	625.90	-
2	FRONT BUMPER SIDE RETAINER L/R @\$25.00 (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT BUMPER SPONGE (CONSISTENT)	CRACKED	326.50	118.00
1	FRONT BUMPER TOW HOOK COVER (CONSISTENT)	CUT	21.00	21.00
1	FRONT GRILLE (CONSISTENT)	CRACKED	356.20	356.20
1	FRONT GRILLE 'LOGO' EMBLEM (CONSISTENT)	NECESSARY	64.90	64.90
2	FRONT HEADLAMP L/R @\$489.90 (CONSISTENT)	O/S CRACKED	979.80	489.90
2	FRONT HEADLAMP LOWER GARNISH L/R @\$320.00 (CONSISTENT)	O/S DEFORMED	640.00	320.00
	LESS 10% DISCOUNT		-360.58	-196.15
			3,245.22	1,765.35
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	80.00	30.00
1	FRONT BUMPER NUMBER PLATE (SN) (CONSISTENT)	DAMAGED	25.00	25.00
1	FRONT BUMPER NUMBER PLATE HOLDER (SN) (CONSISTENT)	DAMAGED	50.00	30.00
			155.00	85.00
<u>LABOUR</u>				
	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING (TO FR).		80.00	30.00
	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT .		500.00	200.00
	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT .		600.00	300.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	80.00	-
			1,260.00	530.00
GRAND TOTAL			4,660.22	2,380.35
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,900.00

Report Ref No. CC4/ASM21013182/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.