

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21013183/TPA3Q2**Date:** 31/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100496687
Claimant Vehicle No :	SHB6353L	Insured Vehicle No :	SDF39K
Date of Loss:	24/12/2021	Nature of Claim:	TP
		Claim No:	8651274917SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB6353L	Engine No:	G4LEKU211721
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Chassis No:	KMHC851CVKU146269
Reg. Date:	30/04/2019 (Man. Year: 2019)	Odometer:	264025 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,236.20	1,062.04	2,174.16	67.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,385.00	515.00	27.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,136.20	2,447.04	2,689.16	52.36
+ GST 7.00/7.00% (S\$)	359.53	171.29	188.24	52.36
Nett Amount (S\$)	5,495.73	2,618.33	2,877.40	52.36
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$120.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,130.33		
Global Sum Settlement (S\$)		3,130.00		

INSPECTION

Date of Assignment:	27/12/2021	
Date Inspected:	27/12/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	430.90 FL	*- FL
2	1		*FRONT BUMPER SIDE BRACKER RH	Not Necessary	35.00 FL	*- FL
3	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*FRONT FENDER RH	Bent	588.80 FL	*588.80 FL
5	1		*FRONT FENDER SHIELD RH	Not Necessary	164.70 FL	*- FL
6	1		*FRONT FENDER BLUE -DRIVE RH	Necessary	26.60 FL	*26.60 FL
7	1		*FRONT WHEEL CAP RH	Cut	346.40 FL	*346.40 FL
8	1		*FRONT BUMPER GRILLE RH	Not Necessary	93.45 FL	*- FL
9	1		*HEADLAMP RH	Not Necessary	1,993.65 FL	*- FL
10	1		*FRT FENDER ADV .STICKER RH	Necessary	100.00 FS	*100.00 FS
11	1		*FRT DOOR ADV STICKER RH	Necessary	100.00 FS	*100.00 FS
12	1		*FRONT DOOR COMFORTDELGRO RH	Necessary	75.00 FS	*75.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,976.50	1,258.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	740.30	196.76
Total Parts (\$\$)	3,236.20	1,062.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	525.00
2	SPRAY PAINTING	New	900.00	750.00
3	CHECK WIRING	New	40.00	0.00
4	TUFF KOTE	New	40.00	30.00
5	WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (\$)			1,900.00	1,385.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >