



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2203057

INV Date 24/05/2022

Reference CC4/LPC21013188/Kpa3q2

Code LPC2

### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 9696S

Insured Veh. GBK 668S

Claim No. 21/21/22/VC05/025290

Policy No. Z21VC05008228

Accident Date 27/12/2021

Inspection Date 28/12/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21013188/Kpa3q2	
			Date: 24/05/2022	
			Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	GBK 668S	<b>Veh. Inspected</b>	SHD 9696S
	<b>Policy No.</b>	Z21VC05008228	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	21/21/22/VC05/025290	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	KENNY	<b>Assign Date</b>	28/12/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	TOYOTA PRIUS (A)	<b>c.c</b>	1798
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
	<b>Chassis No.</b>	JTDKB3FU503082627	<b>Colour</b>	M . P. WHITE / RED
	<b>Odometer</b>	277974 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	195/65 R15	SAILUN	9 mm
	<b>L/H Front Tyre</b>	195/65 R15	SAILUN	9 mm
	<b>R/H Rear Tyre</b>	195/65 R15	SAILUN	3 mm
	<b>L/H Rear Tyre</b>	195/65 R15	SAILUN	3 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	27/12/2021	<b>Inspection Date</b>	28/12/2021
	<b>Survey held at</b>	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9696S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	COVER ,REAR BUMPER	BUCKLED	442.60	442.60
1	REINFORCEMENT SUB-ASSY ,REAR BUMPER	BENT	332.70	332.70
1	COVER ,REAR BUMPER LOWER	DENTED	15.40	15.40
1	GUARD ,REAR BUMPER ,CENTER	BENT	576.30	576.30
1	RETAINER ,REAR BUMPER SIDE ,LH	SERVICEABLE	116.50	-
1	RETAINER ,REAR BUMPER SIDE ,RH	SERVICEABLE	117.70	-
1	PANEL SUB-ASSY ,BACK DOOR	BENT	1,147.80	1,147.80
1	SPOILER SUB-ASSY ,REAR	CRACKED	1,575.40	1,575.40
1	LAM ASSY ,STOP CENTER	CRACKED	192.30	192.30
1	PLATE ,LUGGAGE COMPARTMENT DOOR NAME, NO.2	NECESSARY	54.60	54.60
1	PLATE ,BACK DOOR NAME NO.1	NECESSARY	54.60	54.60
1	ORNAMENT SUB-ASSY ,BACK DOOR	NECESSARY	47.90	47.90
1	GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	CRACKED	925.60	925.60
1	BOARD ASSY ,BACK DOOR TRIM	SERVICEABLE	259.20	-
1	WEATHERSTRIP ,BACK DOOR	SERVICEABLE	372.30	-
1	COVER ,FLOOR UNDER ,NO.1 LH	SERVICEABLE	175.10	-
1	COVER ,FLOOR UNDER ,NO.2 RH	SERVICEABLE	241.90	-
1	COVER ,REAR FLOOR CTR	SERVICEABLE	229.90	-
1	COVER ,DECK TRIM ,REAR	SERVICEABLE	126.70	-
1	PANEL SUB-ASSY ,BODY LOWER BACK	TO REPAIR SEE LABOUR	650.30	-
1	STAY ASSY ,BACK DOOR ,LH	SERVICEABLE	242.50	-
1	STAY ASSY ,BACK DOOR ,RH	SERVICEABLE	242.50	-
1	HINGE ASSY ,BACK DOOR ,LH	TO REPAIR SEE LABOUR	61.00	-
1	HINGE ASSY ,BACK DOOR ,RH	TO REPAIR SEE LABOUR	61.00	-
	LESS 25% DISCOUNT		-2,065.45	-1,341.30
			6,196.35	4,023.90
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET PARKING AID (SN)	DENTED	700.00	220.00

Report Ref No. CC4/LPC21013188/Kpa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIP (SN)	NECESSARY	95.00	50.00
2	WINDSCREEN SEALANT (SN)	NECESSARY	150.00	80.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	200.00	200.00
1	WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	130.00	30.00
1	REAR BUMPER PROTECTOR (SN)	NO SUCH PARTS	180.00	-
1	SET REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	85.00	-
1	REAR SPOILER CLIP (SN)	NOT NECESSARY	70.00	-
1	END PANEL TRIM CLIP (SN)	NOT NECESSARY	65.00	-
1	REAR TAILGATE STICKER 'TRANS-CAB' (SN)	NECESSARY	80.00	30.00
1	REAR TAILGATE STICKER '6555-3333' (SN)	NECESSARY	80.00	30.00
1	REAR NUMBER PLATE WITH MOULDING (SN)	SERVICEABLE	200.00	-
			2,035.00	640.00
	<b>LABOUR</b>			
	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		300.00	180.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.		380.00	60.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY ,BODY LOWER BACK,HINGE ASSY ,BACK DOOR ,LH AND HINGE ASSY ,BACK DOOR ,RH.		2,200.00	500.00
	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		180.00	60.00
	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT ELECTRICAL WIRING ,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	480.00	-
	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	480.00	-
	TO DISMANTLE AND REIFT AIRCON ASSY AND ATTACHMENT,VACUUM AND CHARGE-IN-GAS.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-

Report Ref No. CC4/LPC21013188/Kpa3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	250.00	-
	TOWING FEES.	NOT NECESSARY	150.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,200.00	880.00
	TO REINSTALL REAR BUMPER PARKING SENSOR .		170.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	220.00	-
	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO LIFT-UP /OUT ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS - MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR.	NOT NECESSARY	380.00	-
	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS.	NOT NECESSARY	380.00	-
			10,290.00	1,750.00
<b>GRAND TOTAL</b>			<b>18,521.35</b>	<b>6,413.90</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>6,413.90</b>

Report Ref No. CC4/LPC21013188/Kpa3q2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHD 9696S

### INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SHD 9696S**

**RE-INSPECTION**

