

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21013189/KGA3Q2**Date:** 06/04/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SLN3770A **Insured Vehicle No :** SNA7782J
 Date of Loss: 25/12/2021 Nature of Claim: TP Claim No: MFL2022D0000019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN3770A**
 Make & Model: VOLVO V40, 1.5 T2 (A) Engine No: B4154T51985699
 Reg. Date: 28/04/2017 (Man. Year: 2017) Chassis No: YV1MV28H0H2427507
 Colour: White Odometer: 57904 km
 Engine Capacity: 1498 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm
 Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,818.89	5,237.00	581.89	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,620.00	2,270.00	350.00	13.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,438.89	7,507.00	931.89	11.04
+ GST 7.00/7.00% (S\$)	590.72	525.49	65.23	11.04
Nett Amount (S\$)	9,029.61	8,032.49	997.12	11.04
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		8,739.98		
Global Sum Settlement (S\$)		8,700.00		

INSPECTION

Date of Assignment: 28/12/2021
 Date Inspected: 07/01/2022 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
 160 Sin Ming Drive #04-01, Sin Ming AutoCity
 Singapore 575722
 Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2022)
Parts:	144	VOLVO V40 1.5 T2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN3770A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Bent	2,537.26 F	*2,537.26 FL
2	1		*REAR DOOR LH	Bent	2,469.17 F	*2,469.17 FL
3	1		*REAR DOOR RUBBER SEAL (UPRIGHT) LH	Cut	165.77 F	*165.77 FL
4	1		*SIDE SKIRT LH	Dented / Warped	646.69 F	*646.69 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	5,818.89 5,818.89
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00 581.89
					Total Parts (S\$)	5,818.89 5,237.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK /ERASE FAULT CODES AFTER REPAIR	New	120.00	120.00
2	TO KNOCK DENTS ON FRONT FENDER LH ,REAR SIDE PANEL LH ,ROCKER PANEL LH AND RENEW OF PARTS	New	1,000.00	850.00
3	TO SPRAY PAINT (INCLUDING BLENDING ROOF SIDE PANEL LH)	New	1,500.00	1,300.00
Gross Labour Cost (\$)			2,620.00	2,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >