

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/LCR17011569/K1WB3Q2**Date:** 14/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999995046
<b>Claimant Vehicle No :</b>	SHD6488X	<b>Insured Vehicle No :</b>	SLP284X
Date of Loss:	12/06/2017	Nature of Claim:	TP
		Claim No:	7862647863SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD6488X</b>		
Make & Model:	CHEVROLET EPICA, 2.0 (A)	Engine No:	Z20S1462634K
Reg. Date:	04/05/2012 (Man. Year: 2012)	Chassis No:	KL1LA69RJBB129843
Colour:	Maroon	Odometer:	527360 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,427.00	140.00	1,287.00	90.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,076.00	340.00	736.00	68.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>2,503.00</b>	<b>480.00</b>	<b>2,023.00</b>	<b>80.82</b>
<b>+ Loss of Use (1.5 x S\$60.00/day) (S\$)</b>		90.00		
<b>+ Car Rental (1.5 x S\$113.96/day) (S\$)</b>		170.94		
		<b>(S\$)</b>		
		740.94		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>370.47</b>		
<b>+ Doc/Search Fee (S\$)</b>		5.00		
<b>Nett Liability (S\$)</b>		<b>375.47</b>		
<b>Global Sum Settlement (S\$)</b>		<b>370.00</b>		

INSPECTION

Date of Assignment:	13/06/2017	
Date Inspected:	13/06/2017	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

**Adjuster:** KALVIN ANG WEI KUN**Manager:** ACCUSER4

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SHIELD REAR BUMPER (SN)	Necessary	140.00 F	*140.00 F
2	1		*BUMPER RR	Repair	1,238.00 F	*- F
3	1		*BRACKET RR BUMPER SIDE RH	Serviceable	49.00 F	*- F
					<b>Total Parts (S\$)</b>	<b>1,427.00 140.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	338.00	100.00
2	SPRAY PAINT	New	378.00	200.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
4	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
5	TO REPLACE SUNDRY PARTS	New	100.00	20.00
6	TO WASH AND VACUUM	New	60.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,076.00</b>	<b>340.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >