

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21013192/BPA3Q2**Date:** 15/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070119721-01
Claimant Vehicle No :	SMU4145A	Insured Vehicle No :	SJD6621D
Date of Loss:	26/12/2021	Nature of Claim:	TP
		Claim No:	0813160418SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU4145A		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	1NZX737662
Reg. Date:	12/05/2008 (Man. Year: 2008)	Chassis No:	MR053HY9305060980
Colour:	Grey	Odometer:	211290 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,791.45	1,967.51	6,823.94	77.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	1,400.00	2,900.00	67.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,091.45	3,367.51	9,723.94	74.28
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	13,091.45	2,500.00	10,591.45	80.90
+ GST 7.00/7.00% (S\$)	916.40	175.00	741.40	80.90
Nett Amount (S\$)	14,007.85	2,675.00	11,332.85	80.90
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	27/12/2021	Team Autopro Pte Ltd (sin Ming) (HQ)
Date Inspected:	28/12/2021 Inspected At:	160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
Estimated Period of Repair:	5.0 days	Singapore 575722

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	782.30 FL	*- FL
2	2		*BONNET HINGE	Not Necessary	108.40 FL	*- FL
3	1		*BONNET INNER LOCK	Not Damaged	84.30 FL	*- FL
4	1		*FRONT BUMPER	Broken	658.20 FL	*483.80 FL
5	2		*FRONT BUMPER BRACKET	No such part	374.60 FL	*- FL
6	1		*FRONT BUMPER CENTRE INNER GARNISH	Not Damaged	336.50 FL	*- FL
7	1		*FRONT BUMPER INNER PAD	No such part	314.50 FL	*- FL
8	2		*FRONT BUMPER SIDE RETAINER	Necessary	168.00 FL	*124.00 FL
9	1		*FRONT BUMPER CENTRE GRILLE	Broken	210.00 FL	*190.20 FL
10	1		*FRONT BUMPER FOG LAMP COVER	N/S Broken	291.60 FL	*98.50 FL
11	1		*FRONT BUMPER REINFORCEMENT	Dented	488.60 FL	*312.40 FL
12	1		*FRONT BUMPER TOW COVER	Not Damaged	58.30 FL	*- FL
13	1		*FRONT GRILLE	Broken	320.50 FL	*205.40 FL
14	1		*FRONT GRILLE LOGO	Necessary	85.60 FL	*57.90 FL
15	1		*FRONT GRILLE OUTER CHROME	Cut	85.90 FL	*68.00 FL
16	1		*FRONT SUPPORT PANEL	Repair	652.00 FL	*- FL
17	2		*HEADLAMP	Broken	1,316.40 FL	*976.48 FL
18	2		*HEADLAMP LOWER BRACKET	Not Damaged	297.40 FL	*- FL
19	2		*HEADLAMP TOP BEAM	Not Damaged	621.60 FL	*- FL
20	1		*FRONT AIR GUIDE	No such part	98.00 FL	*- FL
21	1		*AIR CON CONDENSER	Not Damaged	987.20 FL	*- FL
22	1		*RADIATOR	Not Damaged	985.00 FL	*- FL
23	1		*RADIATOR FAN MOTOR	Not Damaged	445.30 FL	*- FL
24	1		*RADIATOR FAN BLADE	Not Damaged	269.80 FL	*- FL
25	1		*RADIATOR FAN ASSY	Not Damaged	588.60 FL	*- FL
26	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
27	1		*BONNET SEALANT	Not Necessary	100.00 FS	*- FS
28	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
29	1		*FRONT BUMPER FOG LAMP COVER CLIPS	Not Necessary	50.00 FS	*- FS
30	1		*FRONT GRILLE CLIPS	No such part	50.00 FS	*- FS
31	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
32	1		*AIR CON FLUID	Not Necessary	80.00 FS	*- FS
33	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
34	1		*HORN	Not Necessary	150.00 FS	*- FS
35	1		*FRONT NUMBER PLATE W/CASING	Bent	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,448.60	2,596.68
- List Item Discount on L Items 25.00/25.00% (\$)	2,657.15	629.17
Total Parts (\$)	8,791.45	1,967.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BONNET COMPONENT	New	200.00	0.00
2	R&R AIR CON CONDENSER	New	150.00	0.00
3	R&R RADIATOR	New	150.00	0.00
4	UPHOLSTERY	New	300.00	0.00
5	CHECK WIRING	New	100.00	0.00
6	PANEL BEATING	New	1,600.00	800.00
7	RUST PROOFING	New	200.00	0.00
8	SPRAY PAINTING	New	1,600.00	600.00
Gross Labour Cost (\$)			4,300.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >