3/14/22, 12:22 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III21013195/KPS3Q2

**Date:** 14/03/2022

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0005172

Claimant Vehicle SHD95K Insured Vehicle No: SNB3278U

No:

Date of Loss: 26/12/2021 Nature of Claim: TP Claim No: MFL2022D0000191

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHD95K

 Make & Model:
 RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)
 Engine No:
 M9R8839C002652

 Reg. Date:
 14/08/2015 (Man. Year: 2015)
 Chassis No:
 VF1ABL15AUC282163

Colour: Metallic White/Red Odometer: 641212 km

Engine Capacity: 1995 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Sailun 9 mm Rear Left Side: Giti 3 mm
Front Right Side: Sailun 9 mm Rear Right Side: Giti 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		13,465.04	6,256.77	7,208.27	53.53
Miscellaneous Items		0.00	0.00	0.00	
Labour		10,240.00	1,910.00	8,330.00	81.35
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	23,705.04	8,166.77	15,538.27	65.55
	Approved Total (Overridden) (S\$)		6,550.00		
	(S\$)	23,705.04	6,550.00	17,155.04	72.37
	+ GST 7.00/7.00% (S\$)	1,659.35	458.50	1,200.85	72.37
	Nett Amount (S\$)	25,364.39	7,008.50	18,355.89	72.37
	+ Loss of Use (5.0 x S\$	640.00/day) (S\$)	200.00		
	+ Car Rental (5.0 x S\$	81.13/day) (S\$)	405.65		
		(S\$)	7,614.15		
	Liable Amour	nt (50.00%) (S\$)	3,807.08		
	+ Doc/S	Search Fee (S\$)	7.45		
	Ne	ett Liability (S\$)	3,814.53		
	Global Sum	Settlement (S\$)	3,800.00		

**INSPECTION** 

Date of Assignment: 28/12/2021

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)

Date Inspected: 28/12/2021 Inspected At: 2, Ang Mo Kio Street 63

Cinanana FC0111

Singapore 569111

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Mar 2022)

Parts: 143 RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD95K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER PANEL REAR RH	Repair	1,933.20 FL	*- FL
2	1		*DOOR PANEL FRT RH	Bent	2,844.66 FL	*1,454.00 FL
3	1		*DOOR WEATHERSTRIP FRT RH	Serviceable	410.70 FL	*- FL
4	1		*DOOR HANDLE OUTER FRT RH	Serviceable	477.76 FL	*- FL
5	1		*DOOR HANDLE MODULE FRT RH	Serviceable	133.60 FL	*- FL
6	1		*DOOR REGULATOR FRT RH	Distorted	505.19 FL	*505.19 FL
7	1		*DOOR REGULATOR MOTOR FRT RH	Jammed	796.46 FL	*796.46 FL
8	1		*DOOR HINGE UPPER FRT RH	Repair	261.28 FL	*- FL
9	1		*DOOR HINGE LOWER FRT RH	Repair	300.55 FL	*- FL
10	1		*DOOR PANEL REAR RH	Bent	2,844.66 FL	*2,844.66 FL
11	1		*DOOR WEATHERSTRIP REAR RH	Serviceable	311.60 FL	*- FL
12	1		*DOOR HANDLE MODULE REAR RH	Serviceable	133.40 FL	*- FL
13	1		*DOOR HANDLE OUTER REAR RH	Serviceable	42.10 FL	*- FL
14	1		*DOOR REGULATOR REAR RH	Repair	450.60 FL	*- FL
15	1		*DOOR REGULATOR MOTOR REAR RH	Repair	758.10 FL	*- FL
16	1		*DOOR HINGE UPPER REAR RH	Repair	241.60 FL	*- FL
17	1		*DOOR HINGE LOWER REAR RH	Repair	169.60 FL	*- FL
18	1		*ROCKER PANEL OUTER RH	Bent	1,184.99 FL	*1,184.99 FL
19	1		*FENDER CLIP	Not Necessary	60.00 FS	*- FS
20	1		*DOOR TRIM CLIP	Not Necessary	70.00 FS	*- FS
21	1		*DOOR SEAL CLIP	Not Necessary	65.00 FS	*- FS
22	1		*DOOR MOULDING CLIP	Not Necessary	70.00 FS	*-FS
23	1		*DOOR STICKER TRANS CAB	Necessary	100.00 FS	*60.00 FS
24	1		*DOOR STICKER 65553333	Necessary	100.00 FS	*60.00 FS
25	1		*DOOR STICKER CLASSIC	Necessary	100.00 FS	*30.00 FS
26	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
27	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
28	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS
F=Fra	ınchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	14,845.05	6,935.30
	- List Item Discount on L Items 10.00/10.00% (S\$)			1,380.01	678.53	
				Total Parts (S\$)	13,465.04	6,256.77

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	1,100.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUS AND REALIGN THE SAME	New ST	6,000.00	700.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	90.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
	Gross Labo	ur Cost (S\$)	10,240.00	1,910.00
	Report was unsubmitted during thi	s print-out.		

< END OF ESTIMATES >