

RESTRICTED

**FINAL COST OF REPAIR**

(To be completed for only one type of item)

To:  HD TPT CENTRE WEST, TPTHUBWEST KEAT HONG NODE  HD TPT WEST S4, TPTHUBWEST CPT CHEONG JIA RONG  <hr style="width: 30%; margin-left: 0;"/>		From:  <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%; text-align: center;">Ref</td> <td style="text-align: center;">20210100534</td> </tr> </table>  MOS 2IC 33FMD  <div style="text-align: right;">Base/LEO Area</div>		Ref	20210100534
Ref	20210100534				
Description of Item:	F550	SAF 1222:	20210100534		
Part/Reg No:	MID34780	Original Value:	-		
Quantity:	01	CE/Non CE:	-		
Description of Damages and Costs of Repairs:		SAF 1204/SAF1351:	8202644854		
		Date:	30 August 2021		
		Accident Job No:	8202644854		
		Date:	29 August 2021		

  

<u>S/N</u>	<u>Incident Repair</u>	<u>Man-hours</u>	<u>Amount</u>
1)	Remove & Install Front Corner Overlap (LHS)	1.0	\$120 -
2)	No Labour to Replace Bolt	-	

  

<u>S/N</u>	<u>Materials Cost</u>	<u>Unit Price</u>	<u>Qty</u>	<u>Cost</u>
1)	FRONT CORNCER OVERLAP (LHS)	\$500	1	\$550
2)	BOLT	\$3	7	\$21

  

<b>Base/LEO Area Office's Assessment of Damages</b>			
Total (labour + spares parts): 7% GST Towing Service Total	= = = =	\$691.00 \$48.37 \$550.36 <b><u>\$1289.73</u></b>	

  

Estimated Time for Repair:	24 Hrs
----------------------------	--------

\*Delete whichever is not applicable

FINAL COST OF REPAIR

RESTRICTED