LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21013198/BVF3E2

Date: 02/09/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001622865

Claimant Vehicle WC3739U Insured Vehicle No : SLR6790B

Date of Loss: 18/12/2021 Nature of Claim: TP Claim No: 267135

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: WC3739U

Make & Model: ISUZU CYH52S, 15.7 D (M) Engine No: 6WG1412300

Reg. Date: 14/10/2010 (Man. Year: 2009) Chassis No: JALCYH52SA7000021

Colour: White Odometer: 391353 km

Engine Capacity: 15681 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 Front Left Side: Firemax 7 mm Rear Left Side: Firemax 7 mm Rear Right Side: Firemax 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		46,164.21	7,519.00	38,645.21	83.71
Miscellaneous Items		0.00	0.00	0.00	
Labour		8,730.00	2,600.00	6,130.00	70.22
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	54,894.21	10,119.00	44,775.21	81.57
	Approved Total (Overridden) (S\$)		8,000.00		
	(S\$)	54,894.21	8,000.00	46,894.21	85.43
	+ GST 7.00/7.00% (S\$)	3,842.59	560.00	3,282.59	85.43
	Nett Amount (S\$)	58,736.80	8,560.00	50,176.80	85.43

INSPECTION

Date Inspected:

Date of Assignment: 28/12/2021

Bifrost Auto Pte Ltd (Kaki Bukit)

8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit

Singapore 415875

Estimated Period of Repair: 8.0 days

Adjuster: Lim Teow Guan Manager: VERON CHEN

28/12/2021 Inspected At:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 02 Sep 2022)

Parts: N/A ISUZU CYH52S 15.7 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for WC3739U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

Condition

Repairer's

Amount

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts No. Qty Part No. Particulars

NO.	Qty	Part No.	Particulars	Condition	Repairer s	Amount
1	1		*REAR AXLE HOUSING	Not Necessary	11,350.50 FL	*- FL
2	1		*REAR AXLE HOUSING SHAFT GASKET	Not Necessary	22.30 FL	*- FL
3	1		*REAR AXLE HOUSING SHAFT	Not Necessary	2,676.00 FL	*- FL
4	1		*REAR AXLE HOUSING SHAFT OIL SEAL (INNER)	Not Necessary	31.80 FL	*- FL
5	1		*REAR AXLE HOUSING SHAFT OIL SEAL (OUTER)	Not Necessary	22.70 FL	*- FL
6	1		*REAR RH WHEEL BEARING (INNER)	Not Necessary	345.80 FL	*- FL
7	1		*REAR RH WHEEL BEARING (OUTER)	Not Necessary	120.78 FL	*- FL
8	1		*REAR RH WHEEL BEARING RETAINER OIL SEAL	Not Necessary	260.40 FL	*- FL
9	1		*REAR RH WHEEL BEARING LOCK PLATE	Not Necessary	22.50 FL	*- FL
10	1		*REAR RH WHEEL BEARING LOCK NUT	Not Necessary	66.00 FL	*- FL
11	1		*REAR RH WHEEL BEARING HUB	Not Damaged	1,590.00 FL	*- FL
12	1		*REAR RH LEAF SPRING	Not Damaged	3,678.00 FL	*- FL
13	2		*REAR RH LEAF SPRING BUSH	Not Damaged	320.70 FL	*-FL
14	1		*REAR RH LEAF SPRING SHACKLE (FRONT)	Not Damaged	545.80 FL	*- FL
15	1		*REAR RH LEAF SPRING SHACKLE (REAR)	Not Damaged	545.80 FL	*- FL
16	2		*REAR RH LEAF SPRING CENTRE U-BOLT	Not Damaged	244.00 FL	*- FL
17	4		*REAR RH LEAF SPRING CENTRE U-BOLT LOCK NUT	Not Damaged	104.00 FL	*- FL
18	1		*REAR RH SHOCK ABSORBER	Not Damaged	448.00 FL	*- FL
19	1		*TORJAN CARRIER ASSY	Not Damaged	4,805.00 FL	*- FL
20	2		*REAR RH TOR ROD	Bent	2,884.00 FL	*790.00 FL
21	1		*REAR RH BRAKE VACUUM PUMP	Not Damaged	2,810.60 FL	*- FL
22	2		*REAR RH BRAKE VACUUM PUMP HIGH PRESSURE HOSES	Not Damaged	640.00 FL	*- FL
23	1		*REAR UNDER-RUN BUMPER	Bent		*1,300.00 FS
23 24	1		*REAR UNDER-RUN BUMPER RH BRACKET	Bent	550.00 FS	*550.00 FS
2 4 25	1					*-FS
25 26	1		*REAR UNDER-RUN BUMPER LH BRACKET	Not Damaged	550.00 FS	- FS *- FS
26 27			*REAR NUMBER PLATE	Not Damaged	70.00 FS	 *-FS
	1		*REAR NUMBER PLATE LAMP	Not Damaged	155.00 FS	
28	1		*RH TAILLAMP	Dislodged	358.00 FS	*358.00 FS
29	1		*RH TAILLAMP BRACKET	Dislodged	220.00 FS	*220.00 FS
30	1		*TAILLAMP WIRE HARNESS	Not Necessary	835.00 FS	*-FS
31	1		*RH REAR WHEEL MUDGUARD	Bent	•	*1,600.00 FS
32	1		*RH REAR WHEEL MUDGUARD MUDFLAP	Bent	220.00 FS	*220.00 FS
33	1		*RH REAR WHEEL MUDGUARD BRACKET	Bent	380.00 FS	*220.00 FS
34	1		*LADDER ASSY	Bent	3,850.00 FS	*800.00 FS
35	1		*LADDER LOWER BRACKET	Bent	220.00 FS	*220.00 FS
36	1		*RH REAR RIM (OUTER)	Bent	680.00 FS	*600.00 FS
37	1		*RH REAR RIM (INNER)	Not Damaged	680.00 FS	*-FS
38	1		*RH REAR TYRE (INNER)	Cut	500.00 FS	*360.00 FS
39	1		*GEAR OIL	Not Necessary	220.00 FS	*- FS
40	1		*BRAKE FLUID	Not Necessary	120.00 FS	*-FS
41	1		*OPEN / CLOSED SWITCH MOTOR ASSY	Not Necessary	2,250.00 FS	*-FS
42	1		*OPEN / CLOSED SWITCH MOTOR BRACKET	Not Necessary	225.00 FS	*-FS
43	1		*RH REAR TYRE (OUTER)	Cut	500.00 FS	*360.00 FS
F=Fra	anchise	part. S=Spo	Nett. L=ListItemDisc.			
				Sub Total (S\$)	49,517.68	7,598.00
			1 !=4 !4=== D!=====4 == 1 . !4==== 4.	0.00/40.000/ /000	0 0 0 0 4 7	70.00

3,353.47

- List Item Discount on L Items 10.00/10.00% (S\$)

79.00

No. Qty Part No. Particulars	Condition	Repairer's	Amount
	Total Parts (S\$)	46,164.21	7,519.00
Report was unsubmitted during	this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labe	our Items			
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND RE-ALIGN ALL AFFECTED PANELS	New	3,200.00	2,000.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,800.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	180.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	280.00	0.00
5	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	1,600.00	0.00
6	CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM	New	350.00	0.00
7	REMOVE, REINSTALL, REPLACE AND RE-ADJUST REAR AXLE HOUSING GEARS TO NEW AXLE HOUSING	New	750.00	0.00
8	REMOVE, CHECK AND REINSTALL AIR COMPRESSOR HOSES TO ASSIST REPAIR	New	350.00	0.00
9	REMOVE, CHECK AND REPLACE REAR WIRE HARNESS TO ASSIST REPAIR	New	220.00	0.00
	Gross Labour	8,730.00	2,600.00	
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >