

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21013199/BTF3N2**Date:** 18/03/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001374562

Claimant Vehicle No : SND31Z**Insured Vehicle No :** SDT113E

Date of Loss: 25/12/2021

Nature of Claim: TP

Claim No: 267440

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SND31Z**

Make & Model: HYUNDAI IONIQ EV FL SR, 1.6 (A)

Engine No: HIDDEN

Reg. Date: 09/12/2021 (Man. Year: 2021)

Chassis No: KMHKM81CRNU045856

Colour: White

Odometer: 996 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/45R20

Rear Tyre Size: 255/45R20

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,095.70	1,046.17	6,049.53	85.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	400.00	3,400.00	89.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,895.70	1,446.17	9,449.53	86.73
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	10,895.70	1,150.00	9,745.70	89.45
+ GST 7.00/7.00% (S\$)	762.70	80.50	682.20	89.45
Nett Amount (S\$)	11,658.40	1,230.50	10,427.90	89.45

INSPECTION

Date of Assignment: 28/12/2021

Date Inspected: 28/12/2021 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)

8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Mar 2022)
Parts:	192	HYUNDAI IONIQ EV FL SR 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND31Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TORSION AXLE COMPLETE	Not Damaged	2,274.91 FL	*- FL
2	1		*BUSH-TRAIL ARM	Not Damaged	437.41 FL	*- FL
3	1		*SHOCK ABSORBER ASSY-REAR RH	Not Damaged	834.60 FL	*- FL
4	1		*SPRING-RR RH	Not Damaged	307.08 FL	*- FL
5	1		*BRACKET SHOCK ABSORBER MOUNTING RH	Not Damaged	236.89 FL	*- FL
6	1		*HUB & BEARING ASSEMBLY-REAR RH	Not Damaged	843.82 FL	*- FL
7	1		*REAR BEARING SENSOR RH	Not Damaged	377.58 FL	*- FL
8	1		*WHEEL ASSY-ALUMINIUM RH	Not Damaged	1,497.47 FL	*- FL
9	1		*COVER-REAR BUMPER	Broken	826.81 FL	*826.81 FL
10	1		*COVER-RR BUMPER SIDE UNDER RH	Broken	102.60 FL	*102.60 FL
11	2		*COVER-REAR BUMPER RETAINER	Necessary	105.84 FL	*74.00 FL
12	2		*COVER-REAR BUMPER STAY	Broken	237.84 FL	*115.00 FL
13	1		*GUARD ASSEMBLY-REAR WHEEL REAR RH	Broken	224.28 FL	*189.30 FL
14	1		*REAR RH TYRE	Not Damaged	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,757.13	1,307.71
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,661.43	261.54
Total Parts (\$\$)	7,095.70	1,046.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR ON DAMAGE AND AFFECTED AREA	New	500.00	200.00
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA	New	500.00	200.00
3	DISMANTLE AND UNDER-CARRIAGE COMPONENTS	New	200.00	0.00
4	APPLY TUFF COATING TREATMENT	New	300.00	0.00
5	PERFORM DIAGNOSTIC CHECK	New	150.00	0.00
6	WHEEL ALIGNMENT	New	150.00	0.00
7	TO CARRY OUT DISCHARGE PROCESS OF CURRENT BEFORE REPAIRS	New	1,000.00	0.00
8	TO CALIBRATE SYSTEM	New	1,000.00	0.00
Gross Labour Cost (\$\$)			3,800.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >