

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013210/DNY3E2**Date:** 15/06/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00029022102
Claimant Vehicle No :	SJB1953P	Insured Vehicle No :	SMJ2407R
Date of Loss:	26/12/2021	Nature of Claim:	TP
		Claim No:	SNM21D207613/C03/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB1953P	Engine No:	65804057
Make & Model:	PORSCHE CAYMAN, 2.7 (A)	Chassis No:	WPOZZZ98Z8U751028
Reg. Date:	03/01/2008 (Man. Year: 2007)	Odometer:	123255 km
Colour:	Black		
Engine Capacity:	2687 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	235/50 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	64,867.04	32,125.98	32,741.06	50.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,240.00	3,050.00	4,190.00	57.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	72,107.04	35,175.98	36,931.06	51.22
Approved Total (Overridden) (S\$)		28,000.00		
(S\$)	72,107.04	28,000.00	44,107.04	61.17
+ GST 8.00/8.00% (S\$)	5,768.56	2,240.00	3,528.56	61.17
Nett Amount (S\$)	77,875.60	30,240.00	47,635.60	61.17

INSPECTION

Date of Assignment:	29/12/2021	
Date Inspected:	28/12/2021	Inspected At: Team Auto Pro Pte Ltd - Sin Ming (HQ) 160 Sin Ming Drive #01-14 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	21.0 days	

Adjuster: BRYAN TANI**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jun 2023)
Parts:	M1-COUPE	PORSCHE CAYMAN 2.7 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJB1953P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	3,798.30 FL	*- FL
2	2		*REAR BUMPER SIDE RETAINER	Necessary	264.40 FL	*217.50 FL
3	2		*REAR BUMPER BRACKET	Not Necessary	397.60 FL	*- FL
4	1		*REAR FENDER RH	Necessary	5,835.40 FL	*2,930.00 FL
5	1		*REAR FENDER INNER COWLING RH	Torn	448.30 FL	*158.60 FL
6	1		*REAR FENDER AIR VENTS GARNISH RH	Missing	478.90 FL	*290.00 FL
7	1		*REAR FENDER INNER TRIM BOARD RH	Not Necessary	580.40 FL	*- FL
8	1		*FRONT DOOR RH	Not Necessary	3,658.60 FL	*- FL
9	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	447.60 FL	*- FL
10	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	578.30 FL	*- FL
11	1		*SIDE MIRROR ASSY RH	Not Necessary	1,822.56 FL	*- FL
12	1		*ROCKER PANEL RH	Buckled	3,722.50 FL	*819.61 FL
13	1		*TAILLAMP RH	Not Necessary	1,078.60 FL	*- FL
14	1		*TAILLAMP LOWER BRACKET RH	Not Necessary	154.00 FL	*- FL
15	1		*EXHAUST PIPE	Dented	4,800.00 FL	*1,460.00 FL
16	1		*EXHAUST MUFFLER VALUE	Not Necessary	3,650.00 FL	*- FL
17	6		*EXHAUST MUFFLER MOUNTING	Not Necessary	768.00 FL	*- FL
18	1		*EXHAUST HEAT SHIELD	Deformed	733.00 FL	*285.00 FL
19	2		*REAR LOWER ARM	Cracked	5,640.80 FL	*1,960.00 FL
20	2		*REAR CONTROL ARM	Malfunction	1,578.60 FL	*1,578.60 FL
21	2		*REAR TRUST ARM	Buckled	1,706.40 FL	*1,706.40 FL
22	2		*REAR SHOCK ABSORBER	Deformed	5,244.20 FL	*2,810.20 FL
23	2		*REAR KNUCKLE ARM	Cracked / Deformed	3,291.00 FL	*3,291.00 FL
24	2		*REAR KNUCKLE ARM BEARING	Necessary	1,197.00 FL	*700.00 FL
25	2		*REAR UPPER ARM	Bent	1,576.20 FL	*1,576.20 FL
26	1		*REAR CROSSMEMBER	Bent	2,513.50 FL	*2,513.50 FL
27	2		*REAR ABS SENSOR	Broken	985.80 FL	*985.80 FL
28	1		*AIRBAG SENSOR RH	Malfunction	589.30 FL	*589.30 FL
29	1		*AIRBAG CONTROL MODULE	Malfunction	6,801.90 FL	*6,801.60 FL
30	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
31	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
32	2		*REAR BUMPER REVERSE SENSOR	Not Necessary	500.00 FS	*- FS
33	1		*REAR FENDER SEALANT	Necessary	100.00 FS	*40.00 FS
34	1		*REAR FENDER INNER COWLING CLIPS	Cracked / Deformed	50.00 FS	*30.00 FS
35	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*FRONT DOOR SEALANT	Not Necessary	100.00 FS	*- FS
37	1		*SIDE MIRROR ASSY SEAL	Not Necessary	60.00 FS	*- FS
38	1		*ROCKER PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
39	1		*TAILLAMP SEAL	Necessary	60.00 FS	*20.00 FS
40	1		*TAILLAMP CLIPS	Not Necessary	50.00 FS	*- FS
41	2		*ORIGINAL PORCHSE PAINT PROTECTION FILM	Necessary	1,500.00 FS	*1,200.00 FS
42	2		*REAR ALLOY RIM	Cracked	2,900.00 FS	*2,400.00 FS

Report was unsubmitted during this print-out.

6/15/23, 4:39 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	2		*REAR TYRE	Cut	1,360.00 FS	*800.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					71,301.16	35,193.31
- List Item Discount on L Items 10.00/10.00% (S\$)					6,434.12	3,067.33
Total Parts (S\$)					64,867.04	32,125.98
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R REAR BUMPER REVERSE SENSOR	New	100.00	0.00
2	R&R FRONT DOOR COMPONENT	New	150.00	0.00
3	R&R REAR UNDER CARRIAGE	New	300.00	250.00
4	R&R REAR TYRE AND BALANCING	New	100.00	60.00
5	R&R EXHAUST PIPE	New	80.00	80.00
6	WHEEL ALIGNMENT	New	180.00	80.00
7	CHECK WIRING	New	100.00	0.00
8	UPHOLSTERY	New	300.00	0.00
9	CONDUCT WATER LEAK TEST	New	180.00	0.00
10	DIAGNOSTIC RESET FAULT CODE	New	300.00	200.00
11	PANEL BEATING	New	2,200.00	1,600.00
12	RUST PROOFING	New	200.00	30.00
13	SPRAY PAINTING	New	2,000.00	600.00
14	R&R AIRBAG CONTROL MODULE	New	250.00	150.00
15	DIAGNOSTIC PROGRAMMING AIRBAG CONTROL MODULE	New	800.00	0.00
Gross Labour Cost (\$\$)			7,240.00	3,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >