

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21013212/R1TF3E2

**Date:** 25/01/2022

### REFERENCE

Insured/Claimant: SIH GEK HUI ANN MRS ANN TEO-SIH GEK HUI  
Date of Loss: 27/12/2021

Policy No: 1800009211

Nature of Claim: OD Claim No: 2573151853SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW2842K	Engine No:	3A92UGP3340
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AJH001033
Reg. Date:	05/02/2018 (Man. Year: 2017)	Odometer:	19858 km
Colour:	Grey		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$51,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre tread depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,776.10	2,900.63	875.47	23.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	2,790.00	1,340.00	32.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,906.10</b>	<b>5,690.63</b>	<b>2,215.47</b>	<b>28.02</b>
<b>- Excess (S\$)</b>	<b>1,600.00</b>	<b>1,600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>6,306.10</b>	<b>4,090.63</b>	<b>2,215.47</b>	<b>35.13</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>441.43</b>	<b>286.34</b>	<b>155.09</b>	<b>35.13</b>
<b>Nett Amount (S\$)</b>	<b>6,747.53</b>	<b>4,376.97</b>	<b>2,370.56</b>	<b>35.13</b>

### INSPECTION

Date of Assignment: 28/12/2021

Date Inspected: 30/12/2021 Inspected At:

Estimated Period of Repair: 5.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

**Adjuster:** MOHD RASUL

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
2	1		*EMBLEM ECO	Necessary	17.00 FS	*17.00 FS
3	1		*HEADLAMP ASSY, LH	Cracked	663.00 FL	*663.00 FL
4	1		*LAMP ASSY, FOG, FR LH	Not Necessary	305.00 FL	*- FL
5	1		*BRACKET, FR BUMPER, LH	Not Necessary	13.00 FL	*- FL
6	1		*GARNISH, FR BUMPER, LH	Scratched	127.00 FL	*127.00 FL
7	1		*AIR DAM, SIDE, FR LH	Not Necessary	18.00 FL	*- FL
8	1		*GRILLE, FR UNDER	Not Necessary	165.00 FL	*- FL
9	1		*BRACKET, FR BUMPER, RH	Not Necessary	13.00 FL	*- FL
10	1		*COVER, HEADLAMP SUPT PANEL	Not Necessary	62.00 FL	*- FL
11	1		*FACE, FR BUMPER	Deformed	706.00 FL	*706.00 FL
12	1		*MARK, THREE-DIA	Necessary	70.00 FL	*70.00 FL
13	1		*GRILLE, RADIATOR	Scratched	557.00 FL	*557.00 FL
14	1		*FENDER, FR LH	Bent	500.00 FL	*500.00 FL
15	1		*PANEL ASSY, FR END	Bent	1,055.00 FL	*1,055.00 FL
16	1		*PANEL, HEADLAMP SUPPORT, UPR	Not Necessary	66.00 FL	*- FL
17	1		*REINFORCEMENT, FR BUMPER	Not Necessary	469.00 FL	*- FL
18	1		*PANEL, AIR GUIDE, LH (Supplementary)	Cracked	11.00 FL	*11.00 FL
19	6		*RIVET, FR BUMPER (Supplementary)	Necessary	30.00 FL	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,887.00	3,756.00
- List Item Discount on L Items 23.00/23.00% (S\$)	1,110.90	855.37
Total Parts (S\$)	3,776.10	2,900.63

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE FRT BUMPER, FRT LH FENDER, SUPPORT & AFFECTED AREA	New	1,800.00	900.00
2	PAINT WORK ON FRT BUMPER, FRT LH FENDER & FRT SUPPORT	New	1,050.00	700.00
3	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR	New	120.00	120.00
4	TO TOP UP AIRCON GAS	New	80.00	80.00
5	PERFORM RUST PREVENTION	New	80.00	40.00
6	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
8	TO SUPPLY FRT NUMBER PLATE WITH FRAME	New	50.00	0.00
9	REPLACE FRONT SUPPORT PANEL (Supplementary)	New	450.00	450.00
10	SPRAY PAINT FRONT SUPPORT PANEL (Supplementary)	New	350.00	350.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,130.00</b>	<b>2,790.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >